CERTIFICATE OF LOCATION OF GOVERNMENT CORNER	
#33 Meander Corner of SectionS 11/14 Township 141 , Range 28 , 5th P.M.	
STATE OF MINNESOTA, County of Cass	
At the corner location shown on the sketch:	
Dx On 10/30/91 found o 1 inch iron pipe with brass cap up 9 inches	
☑ left monument as found, □ lowered monument, □ removed monument (explain)	
Onplaced a	
Magnetic Decl: 5° East SKETCH OF R Not to Scale	EFERENCE TIES All distances are horizontal to nail in side of tree
(1918 GLO BT) 18" Burr Oak N 43 W 276.54'	
	Monument Stamped T141N R28W
	$\frac{\mathtt{S11}}{\mathtt{S14}}\setminus$ MC
8" Burr Oak	1918
N 70 W 59.05'	
_	
Monument is located 75'± southerly of marsh and	(1971 USFS)
210'± westerly of	9" Burr Oak
water.	S 50 E 30.04' scribe overgrown
(1971 USFS)	,
9" Burr Oak S 39 W 32.74	1
scribe overg	
All bearing trees are scribed, painted with red enamel and marked with a 54-3 (bearing tree) tag.	
Statement of evidence relative to this corner location is on back of page. 334682	
I hereby certify that this document and the data	OFFICE OF THE REGISTER OF DEEDS
contained herein was prepared by me or under my direct supervision.	County of
Menal A Mileila 2/10/92	I hereby certify that this document was filed in the Reg. of Deeds office at 3:40 f. M. on the 13 day of 12 day. A.D., 19 42
Registration No. 17008	Register of Deeds Claudie Kaylor
■ Land Surveyor, □ Professional Engineer	By
☐ County Surveyor, ☐ County Engineer	DOCUMENT NO. 334682

Meander corner #33, Sections 11 and 14, Township 141 North, Range 28 West, Cass County, Minnesota

J 18-19

1874 P.H. Conger, U.S. Deputy Surveyor, originally established this corner position while subdividing Township 141 North, Range 28 West. The notes indicate a wood post was set to mark the corner position and the following witnesses: a 23 inch dead White Pine North 56 degrees West a distance of 117 links.

1918 General Land Office survey, filed at the Secretary of State, shows that no original evidence was found. A 1 inch by 36 inch iron pipe with brass cap was set at the proportional position and another 1 inch by 36 inch iron pipe with brass cap at the shoreline at its present location. Ties for proportional position: an 8 inch White Oak North 43 and 1/4 degrees West a distance of 419 links and a 12 inch White Oak South 48 and 3/4 degrees East a distance of 86 links.

1971 United States Forest Service records in Book 1, page 34 and Book 2, page 70 of Township 141 North, Range 28 West, show that Dennis Bergeron found the iron monument with brass cap inplace and marked new bearing trees: a 6 inch Oak North 61 degrees West a distance of 30.15 feet; an 8 inch Oak South 39 degrees West a distance of 32.74 feet and an 8 inch Oak South 50 degrees East a distance of 30.04 feet and set a 6 foot sign post North 2.15 feet.

1971 and 1979, William Okerman, in number 712, and Milo Stefan, in Document number 246277, file Certificate of Location of Government Corner, based on the 1971 United States Forest Service information.

1991 on October 30, a Landecker & Associates of Walker, Inc., survey crew found 1 inch iron pipe with brass cap, 1918 General Land Office bearing tree now an 18 inch Burr Oak North 43 degrees West a distance of 276.54 feet, the 1971 United States Forest Service bearing trees are as shown on front of this certificate. They marked a new bearing tree and set sign posts as shown on front of this certificate. Landecker & Associates of Walker, Inc., accepts the brass cap monument as a perpetuation of the 1918 General Land Office resurvey proportional position of the meander corner. The 1918 General Land Office brass cap monument was also recovered at the present shoreline position.