| CERTIFICATE OF LOCATION | OF GOVERNMENT CORNER |
|---|--|
| MEANDER CORNER #44 of Section 22 | . Township 140 ,Range 29 , 5th P.M. |
| STATE OF MINNESOTA, County of <u>CASS</u> | |
| At the corner location shawn on the sketch: | |
| ■ On 7-8-91 found a 1/2" IRON PIPE WITH RLS #12684 | |
| ■ left monument as found, □ lowered monument, □ removed monument (explain) | |
| | |
| OnPlaced a | |
| | |
| SKETCH OF REFERENCE TIES | |
| N IXL LAKE | |
| woter's edge | |
| | |
| | |
| who swompy it | |
| area 4 | 35' |
| | nail & DNR disc (up 0.2°) southeast side 7" maple |
| +/- 20' | N 75' E 19.91' |
| | 19.31 |
| | |
| / \ | |
| ,' \ | |
| / \ nail & DNR disc (up 0.6') | |
| / | southwest side 5" b.oak |
| / 19.61' | |
| found noil & washer (up 0.9°) west side 12° b.oak | |
| S 23 W 25.06 | |
| | bearings observed with a compass |
| Statement of evidence relative to this corner location is on back of page. WMA 00355 | |
| I hereby certify that this document and the data | OFFICE OF THE COUNTY RECORDER |
| contained herein was prepared by me or under | County of |
| my direct supervision. | I hereby certify that this document was filed in |
| John D. Walker 3-26-92 SIGNATURE DATE | the Co. recorders office at 3:25 P.M. on the |
| Registration No. 16098 | 10 day of December A.D., 1992 |
| ■ Land Surveyor, □ Professional Engineer | By M S Deputy |
| ☐ County Surveyor, ☐ County Engineer | DOCUMENT NO. 343677 |

Meander Corner No. 44, Section 22, Township 140 North, Range 29 West

The DNR Bureau of Engineering contacted the following for survey information:

Minnesota Secretary of State's Office Cass County Surveyor's Office Gary Stevenson, RLS, Walker, MN Walt Curo, RLS, Hackensack, MN Roger Mustonen, RLS, Hackensack, MN

- 1870 This corner was established by the U.S. General Land Office marked with a post and witnessed by the following bearing trees:

 W. Pine, 24" South 48 West, 25 links (16.5')
- August, The United States Department of the Interior, Bureau of Land Management (hereinafter referred to as the BIM), represented by Hugh B. Crawford, Cadastral Surveyor, determined the meander corner position from remains of the original bearing tree: a fallen, badly decayed white pine with old ax marks and burned out scar on NE face which bears S. 48 W., 25 links. The BIM shows the distance south to the section corner to be 15.94 chains (1052.04') which compares favorable to the original call of 16.00 chains (1056.00').
- 1967 Information from Cass County Land Corner Records state R. F. Schneider, RLS, found an oak stake.
- 1970 August, the plat of <u>WHITE PINE HILLS</u> as surveyed by R. F. Schneider shows an iron pipe 925.64 feet north of the section corner in the vicinity of the meander corner but it is not designated as such.
- August, A field crew of the Department of Natural Resources, Bureau of Engineering, found a 1/2" iron pipe with a plastic cap stamped RLS 12684. The monument was found up 0.2 feet marked with a steel fence post. Remains of a down White Pine and stump with ax marks was found 16.5' southwest.
 - Office computation showed this iron pipe to be 1051.41 feet north of the section corner which agrees with the BIM distance of 1052.04 feet and the GIO distance of 1056 feet.
- 1991 The iron pipe is accepted as the Meander Corner and ties were taken as shown on the face of this certificate.