


CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

North Quarter Corner of Section 9, Township 145, Range 31, 5th P.M.
 STATE OF MINNESOTA, County of Cass

At the corner location shown on the sketch:

- On 10/28/93 found a 1 1/2" capped pipe 34" below highway surface.
DATE
- left monument as found, lowered monument, removed monument (explain)
- On 10/28/93 placed a Mn/DOT Cast Iron Monument above existing capped
DATE
pipe. Top of monument flush with highway surface.

SKETCH OF REFERENCE TIES



Statement of evidence relative to this corner location is on back of page.

357110

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

Robert W. Murray 3-28-94
SIGNATURE DATE

Registration No. 15423

- Land Surveyor, Professional Engineer
- County Surveyor, County Engineer

OFFICE OF THE COUNTY RECORDER

County of CASS

I hereby certify that this document was filed in the Co. Recorders office at 11:50 A.M. on the 26th day of APRIL A.D., 19 94

County Recorder Claudia Kayler

By N.B. MICROFILM, Deputy

DOCUMENT NO. 357110

Statement of Evidence:

**NORTH QUARTER CORNER SECTION 9, TOWNSHIP 145 NORTH,
RANGE 31 WEST, FIFTH PRINCIPAL MERIDIAN**

1875 The original Public Land Survey was run by Benjamin C. Baldwin. A scribed post was set to mark corner and witness ties were recorded:

10" Jack Pine N. 8° W. 120 links

6" Jack Pine S. 16° E. 48 links

1907 John Curo set post from government bearing trees. (Survey Record Book A, pages 282-283)

1913 John Curo found stumps of both government bearing trees and set 1 1/2" x 48" capped pipe for quarter corner. (Survey Record Book D, page 152)

1914 John Curo plats PINE GROVE CEMETERY. Plat shows corner as a large iron monument set.

1975 Okerman Surveying, Inc., found 1 1/2" capped pipe under road surface and established new witness ties:

8" Jack Pine S. 31° W. 42.68 feet

6" Jack Pine N. 58° E. 74.70 feet

Power Pole S. 35° E. 60.07 feet

1992 Murray Surveying, Inc., found 1 1/2" capped pipe down 34" under road surface and Okerman's bearing trees. Accepted pipe for north quarter corner of Section 9.

For information regarding this survey, contact Murray Surveying, Inc., Bemidji, MN.