CERTIFICATE OF LOCATION OF GOVERNMENT CORNER	
NORTHEAST Corner of Section 30 , Township 134 N , Range 30 W , 5th P.M.	
STATE OF MINNESOTA, County of CASS	
At the corner location shown on the sketch:	
On 4/4/94 found a SPIKE 0.6' NORTH OF CENTER LINE OF EAST-WEST C.S.A.H. 34 (DOWN 0.8')	
☐ left monument as found. ☐ lowered monument. ■ removed monument (explain)	
On 4/4/94 Placed a 3/4" × 24" REBAR WITH ALUMINUM CAP STAMPED: "DNR SURVEY MARKER"	
IN PLACE OF SPIKE.	
CALL OF BEELDENICE TIES	
SKETCH OF REFERENCE TIES	
1	
NOTE:	
MONUMENT IS: 0.6 N OF CENTER LINE C.S.A.H. 34	DNR DISC & NAIL
12' E OF CENTER LINE DRIVEWAY N +/- 16' W OF EXTENTION OF CENTER LINE DRIVEWAY S IN LINE WITH OLD FENCE S	SE SIDE POWER POLE (UP 2.5')
CENTER LINE DRIVEWAY S IN LINE WITH OLD FENCE S	N 18° E 51.32'
[] :	
<u> </u>	C.S.A.H. 34
·· *	•• .
***	AAW .
DNR DISC & NAIL NW SIDE 5" JACK PINE	DNR DISC & NAIL
(UP 1.0') S 34" W NE SIDE 8" NORWAY PINE (UP 1.5')	
70.23' \$ 32' E' 86.74'	
NOT TO SCALE BEARINGS OBSERVED WITH A COMPASS	
Statement of suidence relative to this assess tension in an healt of page. DATE 9/27/94	
Statement of evidence relative to this corner location is on back of page. FILE SFT 00039	
I hereby certify that this document and the data	OFFICE OF THE COUNTY RECORDER
contained herein was prepared by me or under	County of <u>CASS</u>
my direct cupervision. 10-17-94	I hereby certify that this document was filed in the Co. recorders office at 10:30 A.M. on the
SIGNATURE DATE Registration No. 16098	22 ml day of <u>Seliman</u> A.D., 1996
Registration No. <u>16098</u>	County Recorder <u>claudine</u> <u>Kuylan</u>
☐ County Surveyor, ☐ County Engineer	DOCUMENT NO 3750/7

Northeast Corner Section 30, Township 134 North, Range 30 West, 5th P.M.

The Department of Natural Resources, Bureau of Engineering (BOE) made the following contacts for corner information:

Minnesota Secretary of State
Cass County Surveyors Office
Landecker & Associates, Walker & Pequot Lakes
Widseth, Smith & Nolting, Brainerd
Area Landowners

1868 This corner was originally established by the U.S. General Land Office Survey. The government notes show the corner marked with a post and witnessed by the following bearing trees:

Bl. Pine 14", S 44° W, 42 links (27.72')

Bl. Pine 12", N 87° W, 29 links (19.14')

Bl. Pine 7", N 78° E, 56 links (36.96')

Bl. Pine 15", \$ 27° E, 54 links (35.64')

1987 David Landecker in a survey of Section 21 located a metal attraction at this corner.

1994 BOE found a PK nail at the surface of the county road. There was a metal attraction under the PK nail. Two very old nails were found down 0.6' and 0.8'. The nails were removed and a 2 1/2" iron pipe was found down 2' laying down. The pipe couldn't be removed without digging up a lot of the asphalt road. The spikes were accepted as marking the corner location and a DNR survey marker was set to perpetuate the section corner.

For information regarding this survey, contact the Minnesota Department of Natural Resources, Bureau of Engineering, Survey Section, 500 Lafayette Road, St. Paul, MN 55155-4029.