

432824

OFFICE OF COUNTY RECORDER

State of Minnesota, County of Cass  
I hereby certify that the within instrument  
was filed in this office for record on the  
8 day of Feb. A.D. 20 01  
at 10:40 O'clock A M and was duly  
recorded as Micro Doc. No. 432824

*Claudia Kayler*  
COUNTY RECORDER *JK*


N-9

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

NORTHEAST Corner of Section 20, Township 133, Range 30  
5 TH Principal Meridian, State of Minnesota, County of CASS

At the corner location shown on the sketch:

- On 12-6-2000 found a 0.5 INCH PIPE  
DATE
- left monument as found     lowered monument     removed monument (explain)
- On 12-6-2000 placed a MINNESOTA HIGHWAY DEPARTMENT CAST IRON MONUMENT  
DATE



= MINNESOTA HIGHWAY DEPARTMENT CAST IRON MONUMENT

Statement of evidence for this corner location is on back of this page.

I hereby certify that this document was researched and prepared by me or under my direct supervision.

Signature *James Klein* Date 1-11-2001 License No. 23668  
Title:  Land Surveyor     Professional Engineer     County Surveyor     County Engineer

Statement of Evidence: Northeast Corner Section 20, Township 133 North, Range 30 West, 5<sup>th</sup> Principal Meridian, Cass County, Minnesota.

The original public land survey was run in 1870 and a wood post was set to mark the corner. Bearing tree ties were made to four black pines.

In 1911, Mr. John Curo set a 2 inch by 3.3 foot galvanized pipe in concrete, over top of a stone with an " X " in it. ( Book A, Page 353-360, and on microfilm Roll 11S, Book 74, Pages 41 and 42 )

In 1915, the corner was recovered ( Book 5, Box 2, Page 13 of County Ditch Survey records )

In 1916, Mr. E. B. Horst found iron set by Curo. ( Roll 10S, Book 54A, Page 1 )

In 1984, Comstock and Davis found a 2 inch iron pipe. A Cass County Cast Iron Monument was placed, and bearing ties were made to four house corners. ( Certificate # 276579 )

On December 6, 2000, The Minnesota Department of Transportation recovered a 0.5 inch iron pipe and the four house ties from 1984. The pipe was removed to search for the called for Cast Iron Monument. None being found, a Minnesota Highway Department Cast Iron Monument was set at the position of the 0.5 inch pipe. The four house ties were reestablished. The Minnesota Department of Transportation accepts this position as the correct location for the corner.

For details and survey analysis, contact the Minnesota Department of Transportation District Surveys Office in Baxter, Minnesota.