CERTIFICA	TE OF LOCATION	OF GO	VERNMENT CO	RNER
EAST QUART	ER Corner of Section 23	,Township	135 N ,Range 31 W	V , <u>5TH</u> <sub>P.M.</sub>
STATE OF MINNESOTA, Cou	unty of <u>CASS</u>			
At the corner location sho	own on the sketch:			
On	found a			
	·	red monument,	☐ removed monumer	nt (explain)
□ on <u>6-17-98</u>	Placed a DSM ON N E	EDGE OF	E-W BRUSHED LIN	1E \$70'N
OF	EDGE OF SWAMP AN	NO = 65'	E OF EDGE OF SW	AMP
	SKETCH OF RE	FFFRENCE TIE	· S	
R	<b>3.12.2.</b>	LI LINEINGE	.5	
#				
<b>Y</b>	\			
ř1 –		DNR RP (	UP I'IN NW SIDE OF 8"s	Ø OAK 3
$\mathcal{X}$			42.40 T	3
		R	80	
SWAMP	CUT LINE .	° 0		
		0000	3450-	
$\sim$	Ctr. 24 Red P	ine Solve	00	
N.		1/2-	DNR RP	UP 0.5'W 5
	1	کم		DBL G"+T"MAPLE
NAD83 CASS CO. COORDINATES		MAIR RD (	J UP 0.5 IN NE 5106 OF 2	~ " M CAN
COOKDINATES		- HAV IN	IF O.5 IN WE SIDE OF -	O SE UAIN
N 222,669.50	$\mathbf{Y}$		Abstract Document #441848	
E 481, 431.34		A7	#441848 IMUTHS OBSERVED WIT	Г⊔ <i>Гъ<b>МР</b>Д</i> <<
Statement of eviden	nce relative to this corner lo			DATE FILE WMA01198
		<del> </del>		The times
I hereby certify that this document and the data contained herein was prepared by me or under		OFFICE OF County of	THE COUNTY RECORDER  Cass	
my direct supervision.	or the or the or	1	rtify that this document	was filed in
John D. Woller 5/31/01		the Co. rec	orders office at 2:36	_
License Number 16098		/lexts day o	- · /	_ A.D., 49 <u>00</u> 1
Land Surveyor,	☐ Professional Engineer	County Rec	hn F. Maeder	,Deputy
☐ County Surveyor,	☐ County Engineer	DOCUMENT	NO. 441848	

## East Quarter Corner Section 23, Township 135 North, Range 31 West

The Department of Natural Resources, Bureau of Engineering contacted the following offices for information regarding this corner:

MN Secretary of State
Cass County Surveyor
Widseth, Smith and Nolting of Brainerd
Landecker and Associates of Pequot Lakes
Landecker and Associates of Walker
Central Minnesota Surveying

1870 The US General Land Office field notes, on file in the Secretary of State's Office, show this corner to be marked with a post, 1 chain north of a swamp and the following bearing trees were marked:

W. Pine 20" S 45° W 49 links (32.34') N. Pine 30" S 88 ½° E 56 links (36.96')

The DNR survey crew searched for the corner at the lost location between section corners. Several large pine stumps were found, but no two could be put together to fit the GLO trees. The lost position falls about 1 chain north of a swamp. A 3/4" x 24" iron rod with a MNDNR SURVEY MARKER cap was set at the lost position of the corner, up 1". The distance to the section corners is 2644.99'.

For more information on our survey in this area please contact MN DNR, Bureau of Engineering, Survey Section, 1601 Minnesota Drive, Brainerd, MN 56425