CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

Center West 1/16th Corner, Section 6, Township 141 North, Range 29 West, of the Fifth Principal Meridian, Cass County, Minnesota. Broken 1" iron pipe is accepted as originally set by the GLO resurvey of 1918. The broken pipe was replaced with a 4' x 2 1/2" galvanized steel pipe with a 3 1/4" stamped bronze cap.

SKETCH OF REFERENCE TIES Sec. 6, T 141 N, R 29 W NOT TO SCALE 24° Cedor N42'W 14.13' to 60d spike in NE Face up 2.4' (1918) 18.17 to 60d spike in North Face up 1.3' (2003) 18.17 to 60d spike in North Face up 1.3' (2003) 18.17 to 60d spike in North Face up 1.3' (2003) 18.17 to 60d spike in North Face up 1.3' (2003) 8' Steel fence post N87E 3.93' up 4.7' with 54-2 and 54-9 signs SET 3.87' up 4.8' with 54-2 a		
Bearings are Grid North, Minnesota Central Zone, measured with a hand compass adjusted to 3° East declination. Abstract Document #480063 Statement of evidence relative to this corner location is on the back of this page I hereby certify that this survey, plan, or report was prepared by me or under my direct supervision and this I may aluly licensed Land Surveyor under the law of the State of Minnesota I hereby certify that this document was filed in the Recorder's office. Time: 9:40 AM Date: 212-2004 Recorder Kollhum Monthly By HV Deputy	NOT TO SCALE 24" Cedar N42"W 14.13' to 60d spike in NE Face up 2.4' (1918) 4' x 2 1/2" Gavanized steepipe with 3 1/4" Bronze coup 0.8' 11" Cedar S37'W 33.95' to 60d spike in	7 1/2" Spruce N82E 18.17' to 60d spike in North Face up 1.3' (2003) N82E 18.17 8' Steel fence post N87E 3.93' up 4.7' with 54-2 and 54-9 signs S2E 3.87' up 4.8' with 54-2 and 54-9 signs Cedar stump 3' High S17W
I hereby certify that this survey, plan, or report was prepared by me or under my direct supervision and that I am a duly Licensed Land Surveyor under the laws of the State of Minuscola I hereby certify that this document was filed in the Recorder's office. Time: 9:40 A.M. Date: 212-2004 Recorder Kollhum M. Dolby Licensed Land Surveyor No. 18089 By ## Deputy	Bearings are Grid North, Minnesota Central Zone, measured with a hand compass adjusted to 3° East declination.	(1918) Abstract Document #480063
County of Cass Supervision and that I am a duly Licensed Land Surveyor under the State of Municipal County of Cass I hereby certify that this document was filed in the Recorder's office. Time: 9:40 A.M. Date: 2-12-2004 Recorder Kollhum M. Morby Licensed Land Surveyor No. 18089 By #W Deputy	Statement of evidence relative to this corner location is on the back of this page	
	report was prepared by me or under my direct supervision and that I am a duly Licensed Land Surveyor under the law of the State of Municeola. Daverne Levelling Date Licensed Land Surveyor No. 16089	I hereby certify that this document was filed in the Recorder's office. Time: 9:40 A.M. Date: 2-12-2004 Recorder Kathun M. Maly By #W. Deputy

Page 1 of 2 Pages

Statement of Evidence

Page 2 of 2

Center West 1/16th Corner, Section 6, Township 141 North, Range 29 West, of the Fifth Principal Meridian, Cass County, Minnesota.

1918: Earl G. Harrington, US Surveyor, set a 1"x36" iron pipe with a brass cap from which he made the following BT's:

10° Cedar

10" Cedar

S21'30'W 26 lks (17.16') N4475'W 22 lks (14.52')

Notes of G.L.O. Resurvey of 1917, Page 182. Said notes are on file with the Secretary of State, Saint Paul, MN. Copies of these notes can be found at the Cass County Surveyor's Office in Walker, MN.

February 2, 2000: R. Main, United States Forest Service, found the G.L.O. iron in place. The cap and 4" of pipe are broke off at ground level. He found and made USFS Book 6, Page 67. the following BT's:

Found Cedar

Found 24" Cedar

New 10" Cedar

(Now a 3' high stump) \$21°30'W

N44°W 22 lks (14.52') S36*W 33.85

26 lks (17.16')

September, 2003: Northern Lights Surveying and Mapping, found the iron in place and the cap near by. Found BT's from 2000. Replaced the G.L.O. monument with a 4' x 2 1/2" Galvanized Steel Pipe with a 3 1/4" bronze stamped cap. Made one new BT and added signs as follows. All BT's are painted and have tags.

7 1/2" Spruce

11" Cedar

24" Cedar N42'W

N82E 18.17' to 60d spike in S37W 33.95' to 60d spike in

14.13' to 60d spike in

North Face up 1.3'

West Face up 2.0°

NE Face up 2.4'

(2003)

(2000)

GLO

8' Steel fence post

S2'E 3.87'

8' Steel fence post N87°E 3.93"

GLO Cedar stump

up 4.8' with 54-2 and 54-9 signs

3' High S17W up 4.7' with 54-2 and 54-9 signs 17.4

The original copy of the notes are on page 73, Book 1 for contract No. 53-6392-3-2 for the USFS and are on file at the Supervisors Office of the Chippewa National Forest in Cass Lake, Minnesota. Copies are in the office of Northern Lights Surveying & Mapping in Grand Rapids, MN.

Coordinates by Static GPS:

Cass County North

Northing = 193,153.51' Easting = 454,178.19

State Plane Coordinate System Minnesota Central Zone NAD 83 (HARN 96)

Y = 1,078,914.06' X = 2.587,156.03

Geodetic Coordinates:

Latitude = 47° 03' 31.8644'N Longitude = 94° 24' 01.7714'W