



A000591541

OFFICE OF THE COUNTY RECORDER
CASS COUNTY, MINNESOTA
CERTIFIED, FILED, AND/OR
RECORDED ON

4/15/2013 10:53:11 AM

AS DOC #: A000591541

PAGES: 2

REC FEES: 0.00

KATHRYN M. NORBY
CASS COUNTY RECORDER

BY SR _____ Dep

I hereby certify that this survey, plan, or report was prepared by me or under my direct supervision, and that I am a duly Licensed Land Surveyor under the laws of the State of Minnesota.

Signature: James Kramer
James Kramer

Date: 3-19-2013

Reg. No. 23668

NAD 1996 (HARN) CASS COUNTY COORDINATES

N= 235716.989 E= 431391.386


CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

INDEX NO. E-9, Northeast CORNER OF SECTION 8, TOWNSHIP 135, RANGE 32,
STATE OF MINNESOTA, COUNTY OF CASS

AT THE CORNER LOCATION SHOWN ON THE SKETCH:

- ON 3-19-2013 FOUND A(N) 1-1/2" pipe down 8"
- LEFT MONUMENT AS FOUND.
- LOWERED MONUMENT.
- REMOVED MONUMENT (EXPLAIN)
- ON _____ PLACED A(N) _____

SKETCH OF REFERENCE TIES



KLD
1120 Industrial Park Road SW
Brainerd, MN 56401
218-829-5333

KRAMER LEAS DELEO
SURVEYING • ENGINEERING • PLANNING
BRainerd ST. CLOUD

Note: Monument is on N-S cl, and 6' S of E cl

STATEMENT OF EVIDENCE RELATIVE TO THIS CORNER LOCATION IS ON BACK OF PAGE

Page 1 of 2 A000591541



Index No. E-9

Statement of Evidence

Northeast Corner of Section 8, T135N, R 32 W, Cass County, Minnesota

- 1866 The Original Government Survey was run and a post was set to mark the corner. Ties were made to four Black Pine.
- 1901 Township road order shows no survey. (CCSO corner card)
- 1903 Township road order shows no survey. (CCSO corner card)
- 1985 Terry Freeman, licensed land surveyor, recovered 1-1/2" iron pipe at the corner location.
- 1987 Walt Curo, licensed land surveyor, indicates recovering a 1-1/2" iron pipe. Ties were made to three Jack Pines, a Certificate of Location was recorded as Document No. 297166.
- 2003 Cass County Surveyors Office indicates recovering a 1-1/2" iron pipe. One 1987 bearing tie was recovered, three additional bearing ties were made to a Jack Pine, Norway Pine and a yield sign.
- 2013 Crews from Kramer Leas Deleo searched the area and recovered a 1-1/2" iron pipe. All four 2003 bearing ties were recovered.
- 2013 On February 19, 2013, James Kramer, PLS #23668, analysis of record and survey information indicates the recovered 1-1/2" iron pipe to be the perpetuation of the original corner.