



A000591933

OFFICE OF THE COUNTY RECORDER
CASS COUNTY, MINNESOTA
CERTIFIED, FILED, AND/OR
RECORDED ON

4/26/2013 11:00:24 AM

AS DOC #: A000591933

PAGES: 2

REC FEES: 0.00

KATHRYN M. NORBY
CASS COUNTY RECORDER

BY SR Dep

Page 1 of 2 A000591933

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

EAST QUARTER Corner of Section 34, Township 141 N, Range 28 W
5th Principal Meridian, State of Minnesota, County of Cass

At the corner location shown on the sketch:


On 2-17-2012 found a 2' IRON PIPE WITH STAMPED BRASS CAP
DATE

left monument as found lowered monument removed monument (explain)

On _____ placed a _____
DATE

Monument is located 75'± Westerly of Easterly edge of Cedar, Spruce, and Balsam swamp, and 500'± Easterly of Lumber Yard.

Monument is stabilized on Northerly side by 8' Steel Sign Post.



Not to Scale

Statement of evidence for this corner location is on back of this page.

I hereby certify that this survey, plan, or report was prepared by me or under my direct supervision and that I am a duly Licensed Land Surveyor under the laws of the state of Minnesota.

Signature Trevor L. Skeesick Date 10-5-2012 License No. 46573
Trevor L. Skeesick MNDOT
Title: Land Surveyor Professional Engineer County Surveyor County Engineer

Statement of Evidence

East Quarter Corner Section 34, Township 141 North, Range 28 West, 5th Principal Meridian, Cass County, Minnesota.

Jan. 1874 P.H.Conger, General Land Office (GLO) Deputy Surveyor, set a post for this corner while subdividing Township 141 North, Range 28 West. The following witnesses are listed:

5" Cedar N 50° E 14 links (9.24 feet)
4" Cedar N 45° W 12 links (7.92 feet)

Said record is on file with the Minnesota Historical Society (MHS), St. Paul, Minnesota, copies are filed with the Cass County Surveyor's Office (CCSO).

March 1913 J.W.Curo, County Surveyor, Curo Field Book No. 37A, page 4, on file at the CCSO, states "ordered by Commissioner Spencer to go to Longville and re-establish section corners for Cass Co". Page 16 states "I look for ¼ corner on E side of Sec 34-141-28 and find the old bearing trees".

June 1917 J.M.Greene, Surveyor, Curo Field Book No. 152, page 13, on file at the CCSO, in running a random line east his notes state "missed ¼ corner south 1.1".

April 1938 A.Johnson, Civilian Conservation Corps, on a Form 874-9 on file at the United States Department of Agriculture, Forest Service, Chippewa National Forest (USFS), Cass Lake office notes the corner is a cedar post 18" above the ground in fair condition set by County Surveyor. The following witnesses are listed:

8" Cedar N 62-1/2° E 19 links (12.54 feet), scribing grown over
6" Cedar N 31-1/2° W 12 links (7.92 feet), ¼S & BT scribing visible

Nov. 1943 J.W.Curo, LS 1428, Curo Field Book No. 448, page 29, on file at the CCSO, runs a random line from the C ¼ of Section 34 easterly to the subject corner and states "1/4 sets N 0.90" and shows it marked by a "2 x 3" cedar post". The following witnesses are listed:

11" Cedar N 64° E 12.00 feet, leans SE
8" Spruce N 64°50' W 14.00 feet
9" Cedar S 22° W 17.70 feet

April 1963 G.Claydon, LS 2848, plat of AUDITOR'S PLAT OF LONGVILLE recorded in the Cass County Recorder's Office (CCRO) as **Doc. No. 173535.5**. The plat portrays the Center ¼ and Center East 1/16 corners of the section with which the subject corner position can be reconstructed.

1987 R.Mustonen, LS 11946, Certificate of Survey on file in the CCSO, indicates the subject corner was set.

Nov. 1988 D.Landecker, LS 17008, under contract with the USFS performed a Dependent Resurvey. He found a 2" iron pipe with a brass cap stamped LS 11946. A Certificate of Location of Government Corner was recorded with the CCRO as **Doc. No. 311945** and a Certificate of Survey recorded as **Doc. No. 312481** on May 31, 1989. The following witnesses were noted:

5" Ash N 50° E 47.16 feet 6" Balsam N 88° E 87.78 feet
7" Cedar S 5° W 32.00 feet 8' sign post East 3.70 feet

Nov. 2005 J.Dresel, LS 20370, Certificate of Survey for the City of Longville Airport on file in the CCSO, indicates the subject corner to be a found USFS brass cap monument on a 2" iron pipe.

Feb. 2012 Minnesota Department of Transportation found a 2" iron pipe with a stamped brass cap as noted in Document No. 311945. No witnesses could provide information contrary to the location of the monument. The recovered and established references for the position are shown on the face of this document.

Trevor Skeesick, LS 46573, accepts the monument as certified in 1988 as the correct location of the corner.

For details and survey analysis, contact the Minnesota Department of Transportation, District Surveys Office in Baxter, Minnesota.