CERTIFICATE OF LOCATION OF GOVERNMENT CORNER	
East Quarter of Section 5 ,Township 133 N. ,Range 31 W. , 5th P.M.	
State of Minnesota, County of Cass	
At the corner location shown on the sketch:	
On 26 Aug 2003 found a 1 inch ODIP, capped RLS 17253, down 0.2 foot,	
on centerline County Road Number 102. ☑ left monument as found □ lowered monument □ removed monument (explain)	
On placed	
SKETCH OF REFERENCE TIES	
NOT TO SCALE	
 	
يَّ ا	
Field Fig. 7.	Field
road	102
Υ	
16d duplex nail up 1.0 feet in S side of Fence Gate Post	Number
43.40 W	
West V	Fence line
68.39 feet	S Fence line O S Fence line
up 2 O feet in S side	1 1 1 1
of 10 inch Box Alder	no
SECTION 5	SECTION 4
C: ald	1
Field NOTE: All bearings are true	Field
Statement of evidence relative to this corner location is on the back of this page.	
I hereby certify that this survey, plan or	A000595289
report was prepared by me or under my direct supervision and that I am a duly	OFFICE OF THE COUNTY RECORDER CASS COUNTY, MINNESOTA CERTIFIED, FILED, AND/OR
	DECORDED ON

Licensed Land Surveyor under the laws of the State of Mingesota.

Terry L. Freeman, Cass County Surveyor
Date 8/7//3 MN License No. 21367

8/9/2013 9:00:38 AM

AS DOC #: A000595289

PAGES: 2 REC FEES: 0.00

KATHRYN M. NORBY CASS COUNTY RECORDER

BY_SR___Dep



Page 2 of 2 A000595289

Index No. 13331C.0-09.0

Statement of Evidence

East Quarter corner Section 5, Township 133 North, Range 31 West, 5th Principal Meridian.

June T. Walker and W. Smith, General Land Office (GLO) Deputy Surveyors set a post for the original corner and referenced it as follows:

6" Aspen S 49° W 3 links (2.0 feet) 8" Aspen N 71°30' E 9 links (5.9 feet) Said records are on file with the Secretary of State, St. Paul, Minnesota, copies are filed with the Cass County Surveyor's Office (CCSO).

June B. Grivna, LS 17253, Central Minnesota Surveying, set 1" ODIP, capped RLS #17253, at prorate position between the Northeast and Southeast corners of Section 5.

Aug. B.Hippen and T. Anderson, technicians, CCSO, records of the CCSO, found a 1 inch iron pipe, capped RLS 17253, 0.2 foot below surface, on centerline of County Road Number 102 and fence line East.

July B.Hippen, technician, CCSO, records of the CCSO, found monument and witnesses from 2003.

The monument, recovered and established references for the position are shown on the face of this document.

Analysis of the recovered record data, field evidence and survey measurements, indicates that the monument recovered by CCSO in 2003 is the accepted location of this corner.

County Coordinates (Cass County South)

Northing 175170.62 Easting 465924.03