



A000608520

OFFICE OF THE COUNTY RECORDER
CASS COUNTY, MINNESOTA
CERTIFIED, FILED, AND/OR
RECORDED ON

12/26/2014 12:47:28 PM

AS DOC #: A000608520

PAGES: 2

REC FEES: 0.00

KATHRYN M. NORBY
CASS COUNTY RECORDER

BY SR Dep TX#: 120163

Page 1 of 2 A000608520

Twp 142 Rge 27 Index No. F.0-05.0

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

North Sixteenth corner of Section 7&8, Township 142 N., Range 27 W., 5th P.M.


State of Minnesota, County of Cass

At the corner location shown on the sketch:

On 29 July 2009 found a 1 inch outside diameter iron pipe with GLO brass cap,
down 3.0 feet, 8 feet± east of centerline Boy Lake Drive.

left monument as found lowered monument removed monument (explain)

On 29 July 2009 placed a 1 1/8 inch outside diameter iron pipe, over GLO
monument, down 0.4 foot, 6 feet± north of trail west of Boy Lake Drive.



NOTE:
All bearings are true

Statement of evidence relative to this corner location is on the back of this page.

I hereby certify that this survey, plan or report was prepared by me or under my direct supervision and that I am a duly licensed Land Surveyor under the laws of the State of Minnesota.

Terry L. Freeman, Cass County Surveyor
Date 12/24/14 MN License No. 21367



Index No. F.0-05.0

Statement of Evidence

North One Sixteenth corner Section 7, Township 142 North, Range 27 West, 5th Principal Meridian.

1920 E.G. Harrington, U.S. Cadastral Engineer, assisted by D.B. Clement, U.S. Surveyor, GLO, Reestablishment of a portion of the Exteriors and Subdivisional Lines Township 142 North, Range 27 West, on file with the Minnesota Historical Society in St. Paul, Minnesota, copies are filed with the CCHD/SO, states "Set an iron post, 3 ft. long, 1 ins. diam., 26 ins. in the ground, for the N. 1/16 sec. cor. with brass cap". Lists the following witnesses:
6" Spruce S 54 3/4° E 48 links(31.68 feet) 8" Spruce N 84 1/4° W 89 links (58.74 feet)

June R. Main, technician, United States Department of Agriculture Forest Service (USFS), T 142N R 27 W Book 1,
1993 page 25, on file in the USFS Cass Lake Office, states Found no evidence of monument or bearing trees.

June B. Hippen, technician and P. Swentkofske, Cass County Highway Department equipment operator, records of the
2009 CCHD/SO, in excavating this search area recovered the 1 inch GLO monument down 3.0 feet leaning East, plumb over base and set 1 1/8 inch outside diameter iron pipe, down 0.4 foot, 8 feet, more or less, East of centerline of Boy Lake Drive, 6 feet, more or less, North of Trail to West. New witnesses as follows:
8" Tamarack S 42° E 104.53 feet Power Pole N 17° E 150.81 feet

Dec. B. Hippen, technician, records of the CCHD/SO, set a mag nail over the 1 1/8 inch iron pipe, 10 feet, more or less,
2014 East of the new centerline of Boy Lake Drive, the 2009 witnesses are all good.

The monument, recovered and established references for the position are shown on the face of this document.

Analysis of the recovered record data, field evidence and survey measurements, indicates that the monument recovered by CCHD/SO in 2009 is the accepted location of this corner.

County Coordinates (Cass County North)

Northing 221244.82

Easting 519694.69