

OFFICE OF THE COUNTY RECORDER CASS COUNTY, MINNESOTA CERTIFIED, FILED, AND/OR RECORDED ON

4/9/2015 10:15:25 AM AS DOC #: A000610756 PAGES: 2 REC FEES: 0.00

KATHRYN M. NORBY CASS COUNTY RECORDER

BY_SR___Dep TX#: 121975

<u> </u>	Twp <u>137</u> Rge <u>31</u> Index No. <u>R.0-17.0</u>
CERTIFICATE OF LOCA	TION OF GOVERNMENT CORNER
Northeast corner of Section 2	7,Township <u>137 N.</u> ,Range <u>31 W,_5th</u> P.M.
State of Minnesota, County of Cass	
At the corner location shown on the sketch:	
On 4 June 2005 found <u>a 1.75 inch outside diameter iron pipe, down 0.3 foot,</u>	
on centerline of County Road Number 25, 2 feet ± South of centerline of 40th St. 図 left monument as found □ lowered monument □ removed monument (explain)	
On placed	removed monument (explain)
SKETCH OF REFERENCE TIES	
Pasture	NOT TO SCALE
16d duplex nail up 1.0 foot in E side of a Power Pole	
	SECTION 23
SECTION 22	16d duplex nail up 1.0 foot in E side of 6 inch Burr Oak
FENCE H	40th Street
	213.88
SECTION 27	PY Open
Pasture	SECTION 26
,	3
NOTE: All bearings are true	16d duplex nail up 1.0 foot in W side of 16 inch Burr Oak
Statement of evidence relative to this corner location is on the back of this page.	
I hereby certify that this survey, plan or	
report was prepared by me or under my	
direct supervision and that I am a duly Licensed Land Surveyor under the laws	
of the State of Minnesota.	
Chry & In	
Terry L. Freeman, Cass County Surveyor	
Date <u>778/13</u> MN License No. 213	367



A000610756

Index No. R.0-17.0

Statement of Evidence

Northeast corner of Section 27, Township 137 North, Range 31 West, 5th Principal Meridian.

R. Cronk, General Land Office (GLO) Deputy Surveyor, notes for the subdivision of Township 137 North, Aug. 1870 Range 31 West, set a post for the original corner and referenced it as follows:

8" W. Birch N 30° E 18 links(11.88 feet) 7" W. Birch

N 37° W 16 links(10.56 feet) 12" W. Birch S 4° E 25 links(16.50 feet) 9" Aspen S 74° W 20 links(13.20 feet)

The above record is on file with the Minnesota Historical Society in St. Paul, Minnesota, copies are filed with the Cass County Highway Department, Surveyor's Office (CCHD/SO).

J.M. Canfield, Cass County Surveyor, Road Calendar A, page 81, on file in the CCHD/SO, indicates corner at Dec. 1898 intersection in road. This road in also shown in Book B, page 32.

June, W.H. Hallett, Surveyor's Report for Township Road Order, on file in the CCHD/SO, indicates a road on the north line of Sections 25 and 26, beginning at the subject corner. 1905

J.W. Curo, LS 1428, Cass County Surveyor, Survey Record #87, Book A, page 174 and Survey Record #89, June Book A, page 178, on file in the CCHD/SO, lists the GLO bearing trees and states "All are gone except the root of 1907 the NW and SW old Gov't bearing trees but we find a long sharp field stone buried in the road centre for the true corner: This stone was placed there by James M. Canfield when he was County Surveyor of Cass County". In Curo Book 99, page 13 he states "Stone in cen of road at corner Secs 22-23-26-27-137-31." On page 15 he begins line north at the subject corner.

May J.W. Curo, LS 1428, Cass County Surveyor, Curo Book 95, page 59, on file in the CCHD/SO, states "Began @ Sharp stone set at true corner to secs 22-23-27-28-137-31. 1908

J.W. Curo, LS 1428, Cass County Surveyor, Survey Record #273, Book B, page 146, on file in the CCHD/SO, Beginning at the true corner to secs 22, 23, 26, 27, T. 137, Rg. 30, previously established by me we run East. Nov. 1908

B. Hippen, technician, records of the CCHD/SO, found 1.75 inch outside diameter iron pipe, down 0.3 foot, on June centerline County Road #25, 2 feet, more or less, south of centerline 40th Street and witnessed as follows: 2005 P. Pole N 22° W 77 74 feet

6" R. Oak N 46° E 66.24 feet 16" B. Oak S 42° E 213.88 feet

B. Hippen, technician and P. Swentkofske, CCHD equipment operator, records of the CCHD/SO, excavated a May 2011 6 foot east-west by 6 foot north-south area based on the recovered pipe. The dig was 3 feet deep, 1 foot past natural soil. No large stones were recovered. The 1.75 inch outside diameter iron pipe, was replaced as found.

The monument, recovered and established references for the position are shown on the face of this document.

Analysis of the recovered record data, field evidence and survey measurements, indicates that the monument recovered by CCHD/SO is the accepted location of this corner.

County Coordinates (Cass County South) Northing 283764.34

Easting 472156.68