



A000629332

OFFICE OF THE COUNTY RECORDER
 CASS COUNTY, MINNESOTA
 CERTIFIED, FILED, AND/OR
 RECORDED ON

3/16/2017 12:35:44 PM

AS DOC #: A000629332

PAGES: 3

REC FEES: 0.00

KATHRYN M. NORBY
 CASS COUNTY RECORDER

BY SR Dep TX#: 137217


Index No. R.0-21.0

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

NORTHEAST Corner of Section 26, Township 144 N, Range 26 W
5th Principal Meridian, State of Minnesota, County of CASS

At the corner location shown on the sketch:

- On _____ found a _____
DATE _____
- left monument as found, lowered monument, removed monument (explain)
- On 9/12/2016 Placed a 3/4" X 24" CAPPED REBAR, STAMPED "MN DNR LS 48249"
DATE _____
FLUSH, AT WESTERLY END OF FENCE EAST



CASS COUNTY
 COORDINATE SYSTEM
 NAD 1983 1996 ADJ.
 N = 269068.025
 E = 572871.698

Statement of evidence for this corner location is on back of this page.

3/2/2017
 WMA00772.00.00.01

I hereby certify that this plan, specification, or report was prepared by me or under my direct supervision and that I am a duly Licensed Land Surveyor under the laws of the State of Minnesota.

SIGNATURE Daniel A. Drusch DATE 3-6-2017 License Number 48249
 DANIEL A. DRUSCH

Title: Land Surveyor Professional Engineer County Surveyor County Engineer

**R.0-21.0****Northeast Corner Section 26, Township 144 North, Range 26 West, 5th P.M.**

The DNR Land Survey Unit contacted the following offices for survey information on this corner:

MN Historical Society
Cass County Recorder, Surveyor, and Highway Department
Itasca County Surveyor
US Forest Service Land Department
Contacted Resident Land Owners for permission and testimony

1876 The U.S. General Land Office (GLO) field notes, on file with the MN Historical Society, describe this corner as a post from which:

A Cedar, 6" diam, bears North 30° West, 13 links distant
A Cedar, 6" diam, bears North 22° East, 33 links distant
An Aspen, 10" diam, bears South 38° East, 9 links distant
A Sugar Maple, 5" diam, bears South 61° West, 9 links distant

1900 A survey conducted by the US Corps of Engineers and on file with the Cass County and Itasca County Survey Office, shows no monument symbol at the corner location.

1939 Air photos, on file with the DNR, show the corner area to be in a wooded area with no visible occupation lines.

1953 A survey conducted by R.W. Fassett, on behalf of the US Forest Service, indicates a 2"x 2" temporary stake was set to mark the corner's location. This information is found in USFS Field Book 1 of 144-26, Page 5, in Cass Lake. Copies found in Cass County Surveyor's Office.

1969 Curt Krause, USFS staff member, found a 2x2 hub rotted off at ground level. A search was conducted for original Bearing trees, but nothing no evidence was found. Information can be found in USFS Field Book 1 of 144-26, Page 5, in Cass Lake. Copies found in Cass County Surveyor's Office.

2016 September, the DNR Survey Unit conducted a search for this corner, but did not find any original evidence of the corner. A GPS position was taken at the westerly end of an old, partially down fence line east. The GPS position was found to measure:

2860.44 ft (GLO = 2640 ft) from the East Quarter Corner Section 23
(1953 USFS = 2861.76 ft)

5749.26 ft (GLO = 5280 ft) from the Northeast Corner Section 23
(1953 USFS = 5728.80 ft)

5400.88 ft (GLO = 5332.80 ft) from the Northeast Corner Section 27
(1953 USFS = 5415.30 ft)



Analysis of the available information led the DNR Land Survey Unit to conclude that the GPS position at the found fence corner marks the location of the corner. It agrees with long-standing lines of occupation.