A000633940

OFFICE OF THE COUNTY RECORDER CASS COUNTY, MINNESOTA CERTIFIED, FILED, AND/OR RECORDED ON

8/31/2017 9:58:30 AM

AS DOC #: A000633940 PAGES: 2 REC FEES: 0.00

KATHRYN M. NORBY
CASS COUNTY RECORDER
BY SR ____ Dep TX#: 140858

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER East Quarter corner of Section 34 ,Township 140 N. ,Range 30 W. , 5th P.M. State of Minnesota, County of Cass At the corner location shown on the sketch: On	Twp <u>140</u> Rge <u>3</u> 0	0_ Index No. X.0-17.0	
State of Minnesota, County of Cass At the corner location shown on the sketch: On	CERTIFICATE OF LOCATION OF GOVERN	IMENT CORNER	
At the corner location shown on the sketch: On	East Quarter corner of Section 34 ,Township 140 N. ,R	Range 30 W. , 5th P.M.	
On			
Define the monument as found Towered monument Temoved monument Temoved monument (explain)	At the corner location shown on the sketch:		
On 11 Aug 2017 placed 7/8 inch outside diameter iron pipe, up 0.3 foot, 6 feet±, east of centerline of 32nd Avenue, 1 foot±, south of fence line. SKETCH OF REFERENCE TIES NOT TO SCALE Pasture Statement of evidence relative to this corner location is on the back of this page.	Onfound		
On 11 Aug 2017 placed 7/8 inch outside diameter iron pipe, up 0.3 foot, 6 feet±, east of centerline of 32nd Avenue, 1 foot±, south of fence line. SKETCH OF REFERENCE TIES NOT TO SCALE Pasture Statement of evidence relative to this corner location is on the back of this page.	□ left manument as found □ lowered manument □ removed manument (explain)		
Pasture Pas			
Pasture Note: All bearings are true Statement of evidence relative to this corner location is on the back of this page.			
SECTION 34 SECTION 35 Pasture SECTION 35 Pasture Wooded NOTE: All bearings are true Statement of evidence relative to this corner location is on the back of this page.			
SECTION 34 SECTION 35 Pasture SECTION 35 Pasture Wooded NOTE: All bearings are true Statement of evidence relative to this corner location is on the back of this page.			
SECTION 34 SECTION 35 Pasture SECTION 35 Pasture Wooded NOTE: All bearings are true Statement of evidence relative to this corner location is on the back of this page.	A B I		
SECTION 34 SECTION 35 SECTION 35 Pasture Wooded NOTE: All bearings are true Statement of evidence relative to this corner location is on the back of this page.	Pasture V	16d duplex nail up 1.0 foot in S. side	
SECTION 34 SECTION 35 Pasture Wooded NOTE: All bearings are true Statement of evidence relative to this corner location is on the back of this page.	Pu	of 4 inch Ash	
SECTION 35 Pasture Pasture Wooded NOTE: All bearings are true Statement of evidence relative to this corner location is on the back of this page.	32	*	
Pasture 16d duplex nail up 1.0 foot in W. side of 12 inch White Oak Wooded NOTE: All bearings are true Statement of evidence relative to this corner location is on the back of this page.	SECTION 34	/"/'\	
Pasture 16d duplex nail up 1.0 foot in W. side of 12 inch White Oak Wooded NOTE: All bearings are true Statement of evidence relative to this corner location is on the back of this page.	1 55 Leet		
Pasture 16d duplex nail up 1.0 foot in W. side of 12 inch White Oak Wooded NOTE: All bearings are true Statement of evidence relative to this corner location is on the back of this page.	AA.U		
Pasture 16d duplex nail up 1.0 foot in W. side of 12 inch White Oak NOTE: All bearings are true Pasture Pasture Pasture 16d duplex nail up 1.0 foot in E. side of 6 inch White Pine Statement of evidence relative to this corner location is on the back of this page.		SECTION 35	
Note: All bearings are true 16d duplex nail up 1.0 foot in W. side of 12 inch White Oak Note: All bearings are true 16d duplex nail up 1.0 foot in E. side of 6 inch White Pine Statement of evidence relative to this corner location is on the back of this page.			
Note: All bearings are true 16d duplex nail up 1.0 foot in W. side of 12 inch White Oak Note: All bearings are true 16d duplex nail up 1.0 foot in E. side of 6 inch White Pine Statement of evidence relative to this corner location is on the back of this page.	38.18 (EV)		
16d duplex nail up 1.0 foot in W. side of 12 inch White Oak Wooded NOTE: All bearings are true Statement of evidence relative to this corner location is on the back of this page.	1/1/2/35	Pasture	
Wooded NOTE: All bearings are true Wooden to this corner location is on the back of this page.	3/12:		
Wooded NOTE: All bearings are true Woodence relative to this corner location is on the back of this page.	I UD 1.0 TOOL III W. SIUE		
All bearings are true Statement of evidence relative to this corner location is on the back of this page.			
All bearings are true Statement of evidence relative to this corner location is on the back of this page.	te / /		
All bearings are true Statement of evidence relative to this corner location is on the back of this page.	Wooded 5 16d du up 1.0	foot in E. side	
		cii wiite File	
I hereby certify that this survey, plan or report was prepared by me or under my	Statement of evidence relative to this corner location is on the back of this page.		
direct supervision and that I am a duly Licensed Land Surveyor under the laws of the State of Minnesota.			
Chuy X De			
Terry L. Freeman, Cass County Surveyor Date 8/36/17 MN License No. 21367			



Page 2 of 2

A000633940

Index No. X.0-17.0

Statement of Evidence

East Quarter corner of Section 34, Township 140 North, Range 30 West, 5th Principal Meridian.

Sept. T.B. Walker, General Land Office (GLO) Deputy Surveyor in the notes of the subdivision of Township140 North,
Range 30 West, set a post for the original corner and referenced it as follows:

8" Aspen S 71° W 18 links (11.88 feet) 7" Blk. Pine S 64° E 22 links (14.52 feet) Said records are on file with the Minnesota Historical Society, St. Paul, Minnesota, copies are filed with the Cass County Highway Department, Surveyor's Office (CCHD/SO).

May J.W. Carmen, Curo Book 92, page 26, on file in the CCHD/SO, states "Go out & locate the S.W. & N.W. corner of Sec 35 – 140 – 30 by myself". Also states "Starting at the S.W of 35 chain up to the N.W. of 35 & set 1/4 & 1/16 corners."

Oct. H.S. Todd, Survey for Birch Lake Twp. Curo Book 73, pages 73, 77 and 81, on file in the CCHD/SO, states "@ 2640 set Hub for Temp ¼ corner. We look here for B.ts. the rest of the day but find nothing." Later move Temp ¼ Hub north 10 feet. Page 81 states "set a 2 x 48 inch galvanized iron pipe for corner".

May J.W. Curo, LS 1428, Curo Book 256, page 42, on file in the CCHD/SO, states "Find 2 ½ x 48" galv. Iron pipe set by Harry Todd 1914 Record". "We find the iron in East wheel track of narrow graded road N-S cap tore off." He notes new witnesses as follows:

9" Poplar S 49°24' W 36.41 feet 12" White Oak S 71°50' E 43.60 feet

April H.J. Curo, LS 3417, Curo Book 256, page 81, on file in the CCHD/SO, indicates a IM in the east wheel tract of old narrow road and lists the 1947 witnesses.

March W.E. Curo, LS 11395, Survey for Ekegren, Curo Book 310, page 33, indicates old pipe lying down, northeast of an old nail, on fence line, 3 feet east of centerline at the subject corner.

July B. Hippen, technician, records of the CCHD/SO, found a 60d spike, down 0.7 foot, 3 feet, more or less, east of centerline 32nd Ave. on fence line to west, set 7/8 inch outside diameter iron pipe, capped RLS 21367, down 0.3 foot, at the lost position, midway and on line between the northeast and southeast corners of section 34, as indicated in the 1914 survey and witnessed as follows:

4" Ash N 55° E 44.09 feet 12" W. Oak S 44° W 38.18 feet 6" W. Pine S 2° E 105.35 feet

The monument, recovered and established references for the position are shown on the face of this document.

Analysis of the recovered record data, field evidence and survey measurements, indicates that the monument set by CCHD/SO in 2017 is the accepted location of this corner.

County Coordinates (Cass County North)

Northing 135186.36 Easting 441724.15