



A000637263

OFFICE OF THE COUNTY RECORDER  
CASS COUNTY, MINNESOTA  
CERTIFIED, FILED, AND/OR  
RECORDED ON

12/21/2017 10:58:55 AM

AS DOC #: A000637263

PAGES: 2

REC FEES: 0.00

KATHRYN M. NORBY  
CASS COUNTY RECORDER

BY SR \_\_\_\_\_ Dep TX#: 143458

Page 1 of 2 A000637263

Twp 137 Rge 29 Index No. P.0-05.0

### CERTIFICATE OF LOCATION OF GOVERNMENT CORNER


East Quarter corner of Section 19, Township 137 N., Range 29 W., 5th P.M.  
State of Minnesota, County of Cass

At the corner location shown on the sketch:

On \_\_\_\_\_ found \_\_\_\_\_

left monument as found     lowered monument     removed monument (explain)

On 19 Dec 2017 placed an 1 inch by 32 inch aluminum tube with aluminum cap,  
up 1.0 foot, at lost position.



NOTE:  
All bearings are true

Statement of evidence relative to this corner location is on the back of this page.

I hereby certify that this survey, plan or report was prepared by me or under my direct supervision and that I am a duly Licensed Land Surveyor under the laws of the State of Minnesota.

Terry L. Freeman, Cass County Surveyor

Date 12/20/17 MN License No. 21367



**Index No. P.0-05.0**

Statement of Evidence

**East Quarter corner of Section 19, Township 137 North, Range 29 West, 5th Principal Meridian.**

- July 1865 T.B. Walker, General Land Office (GLO) Deputy Surveyor in the notes of the subdivision of Township 137 North, Range 29 West, set a post for the original corner and referenced it as follows:  
20" Spruce N 65° W 16 links (10.56 feet) 10" Spruce N 36 E 33 links (21.78 feet)  
Said records are on file with the Minnesota Historical Society, St. Paul, Minnesota, copies are filed with the Cass County Highway Department, Surveyor's Office (CCHD/SO).
- April 1910 J.W. Curo, LS 1428, Survey Record 156, Book A, page 322 and Curo Book 91 page 22, on file in the CCHD/SO, lists GLO witnesses and states "We do not find them and continue North."
- Jan. 1917 A.W. Moulster, LS 967, County Ditch No. 9, Ditch Shelf 5, Book 17, pages 4 and 5, on file in the CCHD/SO, indicates he could not find the corner and Oak post set for corner at midpoint on section line.
- Dec. 2017 B. Hippen, technician, records of the CCHD/SO, found no evidence of wood post or witness trees, set an aluminum Cass County monument at lost position, midway and on line between the Southeast and Northeast corners of Section 19 and witnessed as follows:  
10" Burr Oak N 18° E 31.08 feet 6" Burr Oak S 10° E 9.26 feet  
6" Burr Oak S 70° W 13.75 feet

The monument, recovered and established references for the position are shown on the face of this document.

**Analysis of the recovered record data, field evidence and survey measurements, indicates that the monument set by the CCHD/SO in 2017 is the accepted location of this corner.**

**County Coordinates (Cass County South)**

**Northing 286480.91**

**Easting 519807.54**