



A000652199

OFFICE OF THE COUNTY RECORDER
CASS COUNTY, MINNESOTA
CERTIFIED, FILED, AND/OR
RECORDED ON

8/8/2019 11:09:09 AM

AS DOC #: A000652199

PAGES: 2

REC FEES: 0.00

KATHRYN M. NORBY
CASS COUNTY RECORDER

BY KF Dep TX#: 155513

Page 1 of 2 A000652199

Twp 143 Rge 27 Index No. V.0-25.0

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER


Northeast of Section 36, Township 143 N., Range 27 W., 5th P.M.
State of Minnesota, County of Cass

At the corner location shown on the sketch:

On 16 May 2001 found a 2.5 inch ODIP with brass cap, down 0.1 foot,
On centerline of CSAH #4.

left monument as found lowered monument removed monument (explain)

On 8 Nov 2006 placed a 1 inch Aluminum tube with Aluminum cap, down 0.05
foot, 1' +,- North of new centerline of CSAH #4.



NOTE:
All bearings are true

Statement of evidence relative to this corner location is on the back of this page.

I hereby certify that this survey, plan or report was prepared by me or under my direct supervision and that I am a duly Licensed Land Surveyor under the laws of the State of Minnesota.

Terry L. Freeman, Cass County Surveyor
Date 8/7/19 MN License No. 21367



Statement of Evidence

Northeast corner of Section 36, Township 143 North, Range 27 West, 5th Principal Meridian.

June 1986 K.L. Whitehorn, LS 14677, filed a Certificate of Location of Government Corner in the Cass County Records Office as Document Number 289689.

May 2001 B. Hippen and E. Shelly, technicians, records of the Cass County Highway Department, Surveyor's Office, (CCHD/SO), removed the galvanized steel pipe with brass capped prior to road construction. The monument was damaged during removal and the following witnesses are added:

14" W. Oak N 18° E 115.95 feet 8" Spruce S 46° E 88.36 feet

Nov. 2006 B. Hippen, technician, records of the CCHD/SO, set a 1 inch by 18 inch Aluminum tube with Aluminum cap after completion of road construction from existing witness trees.

July 2019 B. Hippen, technician, records of the CCHD/SO, found the Aluminum capped monument and the 1986 and 2001 witnesses in good condition.

The monument, together with the recovered and established references for the position are shown on the face of this document.

Analysis of the recovered record data, field evidence and survey measurements, indicates that the monument set by CCHD/SO in 2006 is the accepted location of this corner.

County Coordinates (Cass County North)

Northing 232895.07

Easting 546521.00