



A000652797

OFFICE OF THE COUNTY RECORDER
CASS COUNTY, MINNESOTA
CERTIFIED, FILED, AND/OR
RECORDED ON

8/29/2019 10:58:39 AM

AS DOC #: A000652797

PAGES: 2

REC FEES: 0.00

KATHRYN M. NORBY
CASS COUNTY RECORDER

BY SF Dep TX#: 155990

Index No. V.O-25.0

I hereby certify that this document was prepared by me or under my direct supervision and that I am a duly Licensed Land Surveyor under the laws of the State of Minnesota

Paul Herkenhoff
PAUL HERKENHOFF

Date 8/15/19 License No. 45875


CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

NORTHEAST Corner of Section 36, Township 134, Range 32, 5TH P.M.

STATE OF MINNESOTA, County of CASS

At the location shown on the sketch:

- On 4/17/19 found 1/2" IRON PIPE WITH RLS CAP 17253
- left monument as found, lowered monument, removed monument (explain)
- On _____ placed an _____



N= 183025.35 E= 452815.96
 DATUM= CASS COUNTY SOUTH
NAD 83/96 ADJ. US SURVEY FT.

Statement of evidence relative to this corner is on back of page.

Page 1 of 2 A000652797





Index No. V.0-25.0

Statement of Evidence:

Northeast Corner of Section 36, Township 134, Range 32 West, 5th Principle Meridian, Cass County, Minnesota

Jan 1858 E.D. Atwater, General Land Office (GLO) Deputy Surveyor n the survey of the east line of Township 134 North, Range 32 West set a post for the original corner and referenced it as follows:

7" Dead Aspen	N21E	9 links
14" Dead Aspen	N46W	25 links
6" Elm	S70 3/4 E	33 links
12" Aspen	S86W	20 links

2005 Westwood Professional Services noted this corner as being in place, as part of a Certificate of Government Corner Location for the East Quarter Corner of Section 36, recorded as Document Number A000509674, which is on file in the office of the Cass County Recorder.

2019 Kramer Leas Deleo filed a Certificate of Government Corner Location on the East Quarter Corner of Section 25, noting a distance of 2634.14 to the subject corner. Information filed as document number A000650525, which is one file in the office of the Cass County Recorder.

2019 Lakes Area Surveying searched the area for all previous evidence, finding a ½ inch open iron pipe at the corner. This corner is the same corner recovered by Westwood Professional Services and Kramer Leas Deleo. The corner fits closely with local fence occupation and also agrees with GLO distances north and south of the subject corner.

Analysis of the recovered record data, field evidence and survey measurements, indicates that the monument found by Lakes Area Surveying in 2019 is the accepted location of this corner.