Index No. A-B 9

# CASS COUNTY LAND CORNER RECORD

T. 132 R. 29 M. 5TH Coordinates: X _____ Y _____

M.C. # 9 Corner common to sections E. LINE SEC. 5




O = Corner

## EXISTING SURVEYS

### Original Government Survey

Year surveyed 1858

Original monument LOST

### Original Evidence Found

Year of search _____ By _____

Monument found _____

### Bearing Trees

| | | | | |
|---|---|---|---|---|
| Species | OAK | ASH | | |
| Diameter | 8" | 8" | | |
| Bearing | N 31 W | S 20 E | | |
| Distance | 180 LKS | 125 LKS | | |

### Original Bearing Trees Found

| | | | | |
|---|---|---|---|---|
| Species | | | | |
| Diameter | | | | |
| Bearing | | | | |
| Distance | | | | |

### Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

### Evidence of Subsequent Corner Restoration

Year of search _____ By _____

### Bearing Trees, Reference Objects

| | | | | |
|---|---|---|---|---|
| Species | | | | |
| Diameter | | | | |
| Bearing | | | | |
| Distance | | | | |

### Bearing Trees, Reference Objects

| | | | |
|---|---|---|---|
| | | | |
| | | | |
| | | | |
| | | | |

### Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

### Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____