


Index No. E 7

CASS COUNTY LAND CORNER RECORD

T. 133 R. 29 M. 5TH Coordinates: X _____ Y _____
N/4 8 Corner common to sections 5 AND 8



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1870
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing	Trees
<u>R. OAK</u>	<u>R. OAK</u>	
<u>10"</u>	<u>8"</u>	
<u>S 38 1/2 E</u>	<u>N 33 1/2 E</u>	
<u>15 LKS</u>	<u>47 LKS</u>	

Original Bearing Trees Found	Species	Diameter	Bearing	Distance

Subsequent Corner Restoration

Year surveyed 1918 By E. B. HORST
Location filed COUNTY BOOK C P 128
Monument Find old Post - WHICH CHECKS WITH OLD
OAK B.T. - STILL STANDING - SET 2x4 1/2" I.M.

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Aug 2001 B. Grina 17253
Cert. of Svy. shows Mon. Found

Bearing Trees, Reference Objects

Species	_____	_____
Diameter	_____	_____
Bearing	_____	_____
Distance	_____	_____

Bearing Trees, Reference Objects

Species	_____	_____
Diameter	_____	_____
Bearing	_____	_____
Distance	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____
Filed at _____

By _____
Date _____