



T. 133 R. 29 M. 5th Coordinates: X _____ Y _____

NE 19 Corner common to sections 17, 18, 19, 20

W. C. 5 65.12' SOUTH, 280.5' EAST, 533.28' NORTH

EXISTING SURVEYS

Original Government Survey

Year surveyed 1870
Original monument Post W.C. 9.32 Ch. South

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees	
Species <u>BL. PINE</u>	<u>BL. PINE</u>
Diameter <u>8"</u>	<u>N46E</u>
Bearing <u>S58W</u>	<u>6"</u>
Distance <u>30 LKS</u>	<u>38 LKS.</u>

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

○ = Corner

Subsequent Corner Restoration

Year surveyed 1870 By GLO
Location filed _____
Monument W.C. Post 4.75 Ch. East, W.C. Post 8.08 North

Evidence of Subsequent Corner Restoration

Year of search 1915 By JOHN CURO
COUNTY BOOK "B" P 422-432 FND POST SET FROM
OLD GOVT BITS OF SOUTH W. C.

Bearing Trees, Reference Objects			
Species <u>BL. PINE</u>	<u>BL. PINE</u>	<u>ASPEN</u>	<u>BL. PINE</u>
Diameter <u>10"</u>	<u>8"</u>	<u>10"</u>	<u>6"</u>
Bearing <u>S17E</u>	<u>N66 1/2 E</u>	<u>S64W</u>	<u>N43 1/2 E</u>
Distance <u>45 LKS</u>	<u>54 LKS.</u>	<u>54 LKS</u>	<u>123 LKS</u>
<u>(TIES 4.75 EAST)</u>		<u>(TIES 8.08 NORTH)</u>	

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____