Index No. 0-5

CASS COUNTY LAND CORNER RECORD

T. 133 R. 29 M. 5th Coordinates: X _____ Y _____

N 1/16 Corner common to sections 19 AND 20



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____

Original monument _____

Original Evidence Found

Year of search _____ By _____

Monument found _____

Bearing Trees

Species				
Diameter				
Bearing				
Distance				

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed 1998 By CCSO

Location filed _____

Monument Fd. capped I.P. RLS #17253 down 0.2'. IP is 22' W of Fe. line and 26' S of corner fence post. Located 7' E of ℄ 36.

Bearing Trees, Reference Objects

Species	W. Oak	J. Pine	W. Oak	
Diameter	7"	11"	11"	
Bearing	N 37° E	S 43° E	S 63° W	
Distance	69.73'	51.00'	89.67'	

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____