Index No. V7-8

CASS COUNTY LAND CORNER RECORD

T. 133 R. 29 M. 5TH Coordinates: X _____ Y _____

MC Corner common to sections 29, 32

EAST SHORE ISLAND



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____

Original monument _____

Original Evidence Found

Year of search _____ By _____

Monument found _____

Bearing Trees

Species				
Diameter				
Bearing				
Distance				

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed 1949 RESURVEY By B.L.M. (CRAWFORD)

Location filed SEC. OF STATE

Monument 2" IRON POST 3' LONG WITH BRASS CAP

T133N
S29
S32 MC
R29W
1949

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	ELM	ELM		
Diameter	9"	8"		
Bearing	S 56½ E	N 36¼ W		
Distance	20½ LKS	56 LKS		

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____