


Index No. V 9

CASS COUNTY LAND CORNER RECORD

T. 133 R. 29 M. 5TH Coordinates: X _____ Y _____
N.E. 32 Corner common to sections 28, 29, 32, 33



EXISTING SURVEYS

Original Government Survey
 Year surveyed 1870
 Original monument Post

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Species	Bearing	Trees	
<u>W. PINE</u>	<u>W. PINE</u>	<u>W. PINE</u>	<u>W. PINE</u>
Diameter <u>18"</u>	<u>18"</u>	<u>18"</u>	<u>24"</u>
Bearing <u>N 22 E</u>	<u>S 61 E</u>	<u>N 16 1/2 W</u>	<u>S 1 W</u>
Distance <u>95 LKS</u>	<u>132 LKS</u>	<u>189 LKS</u>	<u>89 LKS</u>

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration
 Year surveyed 1949 By B. L. M. (CRAWFORD)
 Location filed SEC. OF STATE
 Monument 2" IRON POST 3' LONG 40" IN GROUND WITH BRASS CAP, T 133N R 29W
529/528 NO ORIG. EVIDENCE
532/533

Evidence of Subsequent Corner Restoration
 Year of search Mar 2002 By J. Kranz #23668
Cert. of Surv. shows more found
Nov. 1905, W. M. Hallett
Surv. report shows survey

1949

Species	Bearing	Trees	Reference Objects
<u>W. OAK</u>	<u>R. OAK</u>	<u>R. OAK</u>	
Diameter <u>8"</u>	<u>6"</u>	<u>6"</u>	
Bearing <u>N 86 3/4 E</u>	<u>S 63 W</u>	<u>N 37 W</u>	
Distance <u>117 LKS</u>	<u>77 LKS</u>	<u>105 1/2 LKS</u>	

Bearing Trees, Reference Objects

_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____

Remonumentation certificate prepared _____ By _____
 Filed at _____ Date _____