


Index No. A 19

CASS COUNTY LAND CORNER RECORD

T. 133 R. 30 M. 5TH Coordinates: X N<sup>1</sup>/<sub>4</sub> 2 Y 2 AND 35-134-30  
Corner common to sections



EXISTING SURVEYS

Original Government Survey

Year surveyed 1858

Original monument POST

Bearing Trees

Species	<u>BR. OAK</u>	<u>BR. OAK</u>		
Diameter	<u>12"</u>	<u>12"</u>		
Bearing	<u>N73<sup>1</sup>/<sub>4</sub>W</u>	<u>S79W</u>		
Distance	<u>210 LKS</u>	<u>224 LKS</u>		

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Monument found \_\_\_\_\_

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1990 By JEFF. BRETT

Location filed \_\_\_\_\_

Monument SET 2"x2"x36" TELESPAR CASS Co. Mo. W/AL. CAP AT LOST POSITION

SET SIGN POST 1 FT NORTH

Bearing Trees, Reference Objects

Species	<u>MAPLE</u>	<u>MAPLE</u>	<u>BIRCH</u>	<u>RED OAK</u>
Diameter	<u>4"</u>	<u>8"</u>	<u>6"</u>	<u>9"</u>
Bearing	<u>N51W</u>	<u>N49E</u>	<u>S79E</u>	<u>S29W</u>
Distance	<u>27.03</u>	<u>28.71</u>	<u>18.09</u>	<u>11.78</u>

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_

Location filed \_\_\_\_\_

Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Cert. Filed 1990 by Jeff Brett, RLS 19095

Doc # 320872

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_

Filed at \_\_\_\_\_ Date \_\_\_\_\_