


Index No. E 21-22

CASS COUNTY LAND CORNER RECORD

T. 133 R. 30 M. 5th Coordinates: X _____ Y _____

M.C. # 10 Corner common to sections 1 AND 12



EXISTING SURVEYS

Original Government Survey

Year surveyed 1870
Original monument lost

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	Bearing	Trees
<u>N. PINE</u>	<u>N. PINE</u>	_____
Diameter <u>24"</u>	<u>12"</u>	_____
Bearing <u>N60E</u>	<u>S79E</u>	_____
Distance <u>24 LKS</u>	<u>37 LKS</u>	_____

Original Bearing Trees Found

Species	Bearing	Trees
_____	_____	_____
Diameter _____	_____	_____
Bearing _____	_____	_____
Distance _____	_____	_____

o = Corner

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	Bearing	Reference Objects
_____	_____	_____
Diameter _____	_____	_____
Bearing _____	_____	_____
Distance _____	_____	_____

Bearing Trees, Reference Objects

Species	Bearing	Reference Objects
_____	_____	_____
Diameter _____	_____	_____
Bearing _____	_____	_____
Distance _____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
PLAT - SYLVAN BEACH
JOHN CURE 1924

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____