


T. 133 R. 30 M. 5TH Coordinates: X _____ Y _____
N 14 14 Corner common to sections 11, 14



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1870
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	<u>OAK</u>	<u>BL. PINE</u>	_____	_____
Diameter	<u>4"</u>	<u>8"</u>	_____	_____
Bearing	<u>N70W</u>	<u>S61E</u>	_____	_____
Distance	<u>14 LKS</u>	<u>29 LKS.</u>	_____	_____

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
PLAT - ZEBROSKI ACRES
MYRON LANDECKER 1981

CERTIFICATE - AL WELLE - MINN DOT - 1977
Doc. #232265
On 3-21-77 Found 3" iron pipe flush.
TIES: 8" White Oak NW 21.10' (1942 BT); 9"
White Oak SE 49.80'; 16" Jack Pine stump SW
157.50' (1942 BT); 14" Red Oak SW 82.00'.
Monument is located at the extended
center of roads East, West & South.