


Index No. N 11

CASS COUNTY LAND CORNER RECORD

T. 133 R. 30 M. 5th Coordinates: X _____ Y _____

Corner common to sections 21, 16



EXISTING SURVEYS

Original Government Survey
 Year surveyed _____
 Original monument _____

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Bearing Trees
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Original Bearing Trees Found
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration
 Year surveyed JUNE 1999 By J. KRAMER #23668
 Location filed RECORDERS OFFICE - CASS Co.
 Monument 1/2" I.P. w/ cap - RLS #3091

Evidence of Subsequent Corner Restoration
 Year of search _____ By _____

Bearing Trees, Reference Objects
 Species Oak P. Pole CFP Fencepost
 Diameter 6"
 Bearing N 20° W N 85° E S 34° E S 10° W
 Distance 40.58' 98.94' 82.13' 68.39'

Bearing Trees, Reference Objects

*distances to S.R.P.'s

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____

Remonumentation certificate prepared _____ By _____
 Filed at _____ Date _____