


Index No. N 23

CASS COUNTY LAND CORNER RECORD

T. 133 R. 30 M. 5TH Coordinates: X _____ Y _____

N 1/4 24 Corner common to sections 13 AND 24



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1870
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	Bearing	Trees
<u>Bl. Pine</u>	<u>Bl. Pine</u>	
<u>N12W</u>	<u>S78E</u>	
<u>10" 2</u>	<u>5" 2</u>	
<u>13 LKS</u>	<u>40 LKS</u>	

Original Bearing Trees Found

Species	Bearing	Trees
_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration

Year of search 10/97 By B. Grinn
Cert. of Surv. shows mon. found

Bearing Trees, Reference Objects

Species	Bearing	Reference Objects
_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____

Bearing Trees, Reference Objects

Species	Bearing	Reference Objects
_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remuneration certificate prepared _____ By _____
Filed at _____ Date _____