

Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____


Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

T. 133 R. 30 M. 5TH Coordinates: X _____ Y _____
NE 19 Corner common to sections 17, 18, 19, 20



EXISTING SURVEYS

Original Government Survey
 Year surveyed 1870
 Original monument Post

Species	Bearing	Trees
<u>Bl. Pine</u>	<u>Bl. Pine</u>	<u>Aspen</u>
<u>8"</u>	<u>8"</u>	<u>10"</u>
<u>56W</u>	<u>57E</u>	<u>N70W</u>
<u>530 LKS</u>	<u>525 LKS</u>	<u>556 LKS</u>

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

O = Corner

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument CCSO & Recorder

Evidence of Subsequent Corner Restoration
 Year of search 1915 By _____
Co. DITCH SURVEY BK 5 BOX 2 OF
Co. DITCH SURVEY BOOKS, PG 13

Bearing Trees, Reference Objects
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Bearing Trees, Reference Objects
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration
 Year surveyed 6/99 By MN/Dot
 Location filed CCSO
 Monument 1/2" IP down 0.5', 2' S. of 4

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____
PLAT - BIG WATER
DEAN ANDERSON 1972

<u>P. Pole</u>	<u>N80°W</u>	<u>136.36*</u>
<u>P. Pole</u>	<u>N68°E</u>	<u>150.56*</u>
<u>Stop Sign</u>	<u>S68°E</u>	<u>54.75</u>
<u>St. Sign</u>	<u>S42°W</u>	<u>42.04</u>

* distance to S.R.P.

PLAT - CASTLE ADDITION TO BIGWATER
DEAN ANDERSON 1972

7/01 CCSO found 1" ODIP, down 0.6', 4' S. & CR #101 and 40'± W. & Bigwater Drive. Also 1999 witnesses, Stop Sign may have moved, added.

6" Elm S 32° E, 80.36 to double nail

-corner GPS 11/4/02 CCSO
1" ODIP, down 0.3', 3'± S. of #101

July 2003 J. Kramer #23668
Cert. at Surv shows Mon. Found

Re monumentation certificate prepared #432822
 Filed at CCSO & Recorder

By MN/Dot #23668
 Date 2/8/01