

Index No. A 23

CASS COUNTY LAND CORNER RECORD

T. 133 R. 31 M. 5TH Coordinates: X _____ Y _____
N¹/₄ 1 Corner common to sections 1 AND 36-134-31

EXISTING SURVEYS

Original Government Survey

Year surveyed 1858
Original monument lost


| Species | Bearing | Trees |
|-------------------------|----------------|-------|
| <u>pine</u> | <u>pine</u> | |
| Diameter <u>9"</u> | <u>8"</u> | |
| Bearing <u>S53W</u> | <u>N71W</u> | |
| Distance <u>10 LKS.</u> | <u>25 LKS.</u> | |

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

| | | |
|----------|--|--|
| Species | | |
| Diameter | | |
| Bearing | | |
| Distance | | |



Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Bearing Trees, Reference Objects

| | | |
|----------|--|--|
| Species | | |
| Diameter | | |
| Bearing | | |
| Distance | | |

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

| | | |
|--|--|--|
| | | |
| | | |
| | | |

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____