


T. 133 R. 31 M. 5TH Coordinates: X _____ Y _____
NE 5 Corner common to sections 4, 5 and 32, 33-34-31



EXISTING SURVEYS

Original Government Survey
 Year surveyed 1858
 Original monument Post

Bearing Trees			
Species	Bearing	Distance	
<u>BL. OAK</u>	<u>N 74 W</u>	<u>30 LKS</u>	
<u>W. BIRCH</u>	<u>N 61 E</u>	<u>32 LKS</u>	
<u>ASPEN</u>	<u>S 11 E</u>	<u>27 LKS</u>	
<u>W. MAPLE</u>	<u>S 18 W</u>	<u>20 LKS</u>	

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration
 Year surveyed 1907 By JOHN CURO
 Location filed COUNTY RECORD BOOK "A" P. 8, 9
 Monument 8X8X36" STONE
1915, N.D. GORMAN, BOOK "B" P. 484-495 FND CORNER
PASSABLE I.M.

Bearing Trees, Reference Objects
 Species POPLAR POPLAR
 Diameter 4" 2"
 Bearing S 9-23 E N 10-10 E
 Distance 33.90' 61.80'

Evidence of Subsequent Corner Restoration
 Year of search 1910 By CURO
microfilm - roll 115 BK 91 P. 36
set 8X8X36" stone monument

1985 - Freeman and Backhoe operator Eileen Williams dug 11' X 11 hole 3' deep

Bearing Trees, Reference Objects
9" class v and road top
2 1/4' natural sandy clay

A 9 Subsequent Corner Restoration
 Year surveyed 10-15-86 By _____
 Location filed _____
 Monument SET CAST IRON MON. IN & DOWN 8"

TELE. DIST.	CFP	PP	SMS
<u>N 52 W</u>	<u>N 45 E</u>	<u>S 41 E</u>	<u>S 45 W</u>
<u>45.00</u>	<u>33.30</u>	<u>50.95</u>	<u>50.0</u>

Filed cert. 1-29-90 by Walter Curo, RLS 11395
Dr. # 318247

3/2001 CCSO found CIM, down 0.7' on & CR #102 and 2' N. & 120th St
Found 1986 witnesses NW & SE, add the following

14" Spruce N 25° E, 94.33*
6" N. Pine S 34° W, 55.43*
* distance to double head nail

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____