


Index No. \_\_\_\_\_

CASS COUNTY LAND CORNER RECORD

T. \_\_\_\_\_ R. \_\_\_\_\_ M. \_\_\_\_\_ Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_

Corner common to sections \_\_\_\_\_



= Corner

EXISTING SURVEYS

Original Government Survey

Original Evidence Found

Year surveyed \_\_\_\_\_

Year of search \_\_\_\_\_ by \_\_\_\_\_

Original monument \_\_\_\_\_

Monument found \_\_\_\_\_

Bearing Trees

Original Bearing Trees Found

Species \_\_\_\_\_

Species \_\_\_\_\_

Diameter \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Distance \_\_\_\_\_

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_

Year of search \_\_\_\_\_ By \_\_\_\_\_

Location filed: \_\_\_\_\_

Location filed: \_\_\_\_\_

Monument: \_\_\_\_\_

Monument: \_\_\_\_\_

Bearing Trees, Reference Objects

Bearing Trees, Reference Objects

Species \_\_\_\_\_

Species \_\_\_\_\_

Diameter \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Distance \_\_\_\_\_

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration Found

Year surveyed \_\_\_\_\_ By \_\_\_\_\_

Year of search \_\_\_\_\_ By \_\_\_\_\_

Location filed: \_\_\_\_\_

Location filed: \_\_\_\_\_

Monument: \_\_\_\_\_

Monument: \_\_\_\_\_

Certificate of Location of Government Corner filed in Cass County

By \_\_\_\_\_


Recorders Office as Document \_\_\_\_\_

Date \_\_\_\_\_

Index No. E 15

CASS COUNTY LAND CORNER RECORD

T. 133 R. 31 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N 1/4 10 Corner common to sections 3 AND 10



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1863  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species	<u>Aspen</u>	<u>Aspen</u>		
Diameter	<u>7"</u>	<u>8"</u>		
Bearing	<u>S5W</u>	<u>N18E</u>		
Distance	<u>15 LKS</u>	<u>8 LKS.</u>		

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 5/19/86 By Freeman, Glen Williams  
Location filed Backhoe  
Monument dig in center of road & fence south  
dig 9' N-S 14' E-W 2' deep  
all gravel & clay - (cut in area)  
SET 2" X 10" TYPAR MON NW 1/4 10

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Bearing Trees, Reference Objects

Species	<u>RBD OAK</u>	<u>PUR POLE</u>	<u>GATE BRACK</u>	<u>MARKER SIGN</u>
Diameter	<u>12"</u>			
Bearing	<u>S29W</u>	<u>S44E</u>	<u>S50E</u>	<u>NORTH</u>
Distance	<u>65.77</u>	<u>48.87</u>	<u>30.75</u>	<u>20</u>

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
L-22-90 Cert. Filed by Walter Cyro, RLS 11395  
Doc. # 317965 showing 1981 information.

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_