

Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____

Original monument _____

Original Evidence Found

Year of search _____ by _____

Monument found _____

Bearing Trees

Species _____

Diameter _____

Bearing _____

Distance _____

Original Bearing Trees Found

Species _____

Diameter _____

Bearing _____

Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed: _____

Monument: _____

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Location filed: _____

Monument: _____

Bearing Trees, Reference Objects

Species _____

Diameter _____

Bearing _____

Distance _____

Bearing Trees, Reference Objects

Species _____

Diameter _____

Bearing _____

Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed: _____

Monument: _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____


Location filed: _____

Monument: _____

Index No. 6 13

CASS COUNTY LAND CORNER RECORD

T. 133 R. 31 M. 5TH Coordinates: X _____ Y _____
E 14 9 Corner common to sections 9 AND 10



EXISTING SURVEYS

Original Government Survey
 Year surveyed 1863
 Original monument Post

Bearing Trees

| | | | |
|----------|--------------|---------------|-------|
| Species | <u>ASPEN</u> | <u>OAK</u> | _____ |
| Diameter | <u>4"</u> | <u>4"</u> | _____ |
| Bearing | <u>N71E</u> | <u>S79W</u> | _____ |
| Distance | <u>8 LKS</u> | <u>12 LKS</u> | _____ |

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found

| | | | |
|----------|-------|-------|-------|
| Species | _____ | _____ | _____ |
| Diameter | _____ | _____ | _____ |
| Bearing | _____ | _____ | _____ |
| Distance | _____ | _____ | _____ |

O = Corner

Subsequent Corner Restoration
 Year surveyed 1915 By E. B. HARST
 Location filed COUNTY BOOK C RBG
 Monument SET 4X4X4" WOOD POST

Evidence of Subsequent Corner Restoration
 Year of search 6/12/03 By CCSO
Found 1/2" P.W., down 1.4', 2' ± E. of E
Co. Rd. #35, 1' ± S. of Fence line West.

Bearing Trees, Reference Objects

| | | | |
|----------|-------|-------|-------|
| Species | _____ | _____ | _____ |
| Diameter | _____ | _____ | _____ |
| Bearing | _____ | _____ | _____ |
| Distance | _____ | _____ | _____ |

Bearing Trees, Reference Objects

| | | | |
|------------------|---------------|----------------|-------|
| <u>COB. Post</u> | <u>W. Oak</u> | <u>W. Oak</u> | _____ |
| | <u>19"</u> | <u>13"</u> | _____ |
| <u>N84°W</u> | <u>S71°W</u> | <u>S53°W</u> | _____ |
| <u>39.15</u> | <u>73.36'</u> | <u>114.73'</u> | _____ |

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found
 Year of search Aug 1911 By _____
Trap rd order shows no survey
May 1911, Trap rd order shows no survey

Remonumentation certificate prepared _____ By _____
 Filed at _____ Date _____