


Index No. 65

CASS COUNTY LAND CORNER RECORD

T. 133 R. 31 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E/4 Corner common to sections 7 and 8



○ = Corner

EXISTING SURVEYS

Original Government Survey  
Year surveyed 1863  
Original monument Post

Original Evidence Found  
Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees  
Species PINE PINE  
Diameter 10" 6"  
Bearing S89 1/2 E S52 W  
Distance 101 LKS. 218 LKS.

Original Bearing Trees Found  
Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration  
Year surveyed 1915 By N.A. GORMAN  
Location filed COUNTY SURVEY BOOK '15' P 490-495  
Monument SET CORNER PROPORTIONALLY.

Evidence of Subsequent Corner Restoration  
Year of search 1985 10/29 By FREEMAN  
Found 2" I.P. FLUSH  
NW 1977 B.T. gone

Bearing Trees, Reference Objects  
Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Bearing Trees, Reference Objects  
\_\_\_\_\_

Subsequent Corner Restoration  
Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found  
Year of search \_\_\_\_\_ By \_\_\_\_\_  
CERTIFICATE - AL WELLE - MINN DOT - 1977  
Doc. # 231312

2-3-77 Found 2" iron pipe flush. TIES: 5"  
White Oak NW 71.54'; 10" Jack Pine SE 72.88';  
12" Jack Pine SW 38.10'. Old fence approx.  
10' North of monument. Monument is located  
in E of road.

Oct. 1894, Twp rd order shows no survey  
Nov. 1914, Twp rd order shows no survey

Remonumentation certificate prepared \_\_\_\_\_  
Filed at \_\_\_\_\_

By \_\_\_\_\_  
Date \_\_\_\_\_