


T. 133 R. 31 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N 1/4 13 Corner common to sections 12 AND 13



EXISTING SURVEYS

**Original Government Survey**

Year surveyed 1863  
Original monument Post

**Bearing Trees**

Species	<u>PINE</u>	<u>PINE</u>	_____
Diameter	<u>9"</u>	<u>9"</u>	_____
Bearing	<u>N 77 3/4 E</u>	<u>S 57 3/4 E</u>	_____
Distance	<u>26 LKS</u>	<u>33 LKS.</u>	_____

**Original Evidence Found**

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

**Original Bearing Trees Found**

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

**Subsequent Corner Restoration**

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

**Evidence of Subsequent Corner Restoration**

Year of search 1985 10/24 By Freeman  
Found cap broke off 1 1/2" up 0.4'  
and the 2 1953 witness pipes

**Bearing Trees, Reference Objects**

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

**Bearing Trees, Reference Objects**

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

**Subsequent Corner Restoration**

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

**Evidence of Subsequent Corner Restoration Found**

Year of search \_\_\_\_\_ By \_\_\_\_\_  
CERTIFICATE - L.C. MAY - MINN DOT - 1953  
Doc. # 258605  
Found an iron pipe. Placed galvanized  
iron monument with aluminum cap. Ties:  
iron monument 55' NE; Iron monument  
55' NW.