

Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____


Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

T. 133 R. 31 M. 5TH Coordinates: X _____ Y _____
NE 17 Corner common to sections 8, 9, 16, 17



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1863
Original monument lost

Original Evidence Found

Year of search _____ By _____
Monument found _____

| Species | Bearing Trees | |
|----------|------------------|---------------|
| | ASPEN | ELM |
| Diameter | <u>7"</u> | <u>8"</u> |
| Bearing | <u>S 9 3/4 E</u> | <u>S 44 W</u> |
| Distance | <u>49 LKS</u> | <u>30 LKS</u> |

Original Bearing Trees Found

| Species | Diameter | Bearing | Distance |
|---------|----------|---------|----------|
| _____ | _____ | _____ | _____ |
| _____ | _____ | _____ | _____ |
| _____ | _____ | _____ | _____ |

Subsequent Corner Restoration

Year surveyed 1910 By JOHN CURD
Location filed COUNTY RECORD BOOK "A" P. 18, 19
Monument TWO OLD GOVT B.T.S. SET 8x8x6" STONE
DL & TRENCH 2.5' DEEP 1' WIDE EXTENDS 3' N. AND
3' E. FILL WITH ROCK & CONCRETE
1915, N.D. GORMAN, COUNTY BOOK "B" P 490-495 FND CORNER

Bearing Trees, Reference Objects

| Species | Diameter | Bearing | Distance |
|---------|----------|---------|----------|
| _____ | _____ | _____ | _____ |
| _____ | _____ | _____ | _____ |
| _____ | _____ | _____ | _____ |

Evidence of Subsequent Corner Restoration

Year of search 1915 By E. B. HORST
COUNTY BOOK "C" P. 84 FND CONCRETE POST
1921, E. B. HORST, BOOK "D" P. 8 FND STONE MONUMENT
SET FROM U.S. B.T.S. - (STILL IN PLACE)

1910 - also on microfilm - roll 115 BK 91 P. 35

Bearing Trees, Reference Objects

| Species | Diameter | Bearing | Distance |
|---------|----------|---------|----------|
| _____ | _____ | _____ | _____ |
| _____ | _____ | _____ | _____ |
| _____ | _____ | _____ | _____ |

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Certificate - Mike Landecker - 1985
Doc. # 280131
Fnd 8" Sq. stone down 1.5' set broke off
Cast iron monument down 0.5' below surface
also Fnd Elm BIT. NW bearing & dist good
8" W oak S 53° W 65.12'
12" Ash N 84° W 76.16'
17" Ash N 47° W 62.03'
12" Ash S 51° E 82.08'
orig Elm 24" N 70° W 34.6 to face blaze - cut down

Sept 1902, Twp rd order shows no survey
May 1902, Twp rd order shows no survey