Index No. L 25

# CASS COUNTY LAND CORNER RECORD

T. 133 R. 31 M. 5TH Coordinates: X _____ Y _____

E 1/4 13 Corner common to sections 13 AND 18-133-30




## EXISTING SURVEYS

### Original Government Survey

Year surveyed 1858

Original monument Post

### Original Evidence Found

Year of search _____ By _____

Monument found _____

### Bearing Trees

| | | | | |
|---|---|---|---|---|
| Species | Pine | Pine | | |
| Diameter | 14" | 14" | | |
| Bearing | N 80 W | N 20 E | | |
| Distance | 9 LKS. | 16 LKS. | | |

### Original Bearing Trees Found

| | | | | |
|---|---|---|---|---|
| Species | | | | |
| Diameter | | | | |
| Bearing | | | | |
| Distance | | | | |

### Subsequent Corner Restoration

Year surveyed 7/97 By B. Grovna

Location filed _____

Monument Set 1/2" iron pipe capped RLS 17253, at old fence intersection. A C of L was filed

### Evidence of Subsequent Corner Restoration

Year of search _____ By _____

### Bearing Trees, Reference Objects

| | | | | |
|---|---|---|---|---|
| Species | J. Pine | Birch | Aspen | Aspen |
| Diameter | 8" | 6" | 12" | 4" |
| Bearing | NNE | ESE | South | WSW |
| Distance | 28.9' | 4.7' | 31.55' | 13.7' |

### Bearing Trees, Reference Objects

L-25

### Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

### Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared #468351 By #17253

Filed at CCRO Date 6/13/03