


Index No. L9

CASS COUNTY LAND CORNER RECORD

T. 133 R. 31 M. 5TH Coordinates: X _____ Y _____
E114 17 Corner common to sections 16 AND 17



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1863
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing	Trees
<u>PINE</u>	<u>ASPEN</u>	
Diameter <u>8"</u>	<u>8"</u>	
Bearing <u>S 74 1/2° E</u>	<u>N 88° W</u>	
Distance <u>71 LKS.</u>	<u>60 LKS.</u>	

Species	Bearing	Trees
_____	_____	_____
Diameter _____	_____	_____
Bearing _____	_____	_____
Distance _____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration

Year of search 1985 By Dave Landecker
Corner Certificate Doc # 285668
Set 2x2x36" sq. iron w/aluminum cap
Survey marker sign 0.3' N. of corner

Bearing Trees, Reference Objects

Species	Bearing	Distance
_____	_____	_____
Diameter _____	_____	_____
Bearing _____	_____	_____
Distance _____	_____	_____

Bearing Trees, Reference Objects

Species	Bearing	Distance
<u>W. oak</u>	<u>R. oak</u>	<u>W. oak</u>
<u>4"</u>	<u>14"</u>	<u>9"</u>
<u>N 45° W</u>	<u>N 55° E</u>	<u>N 87° E</u>
<u>71.00'</u>	<u>267.41'</u>	<u>237.40'</u>
		<u>N. Pine</u>
		<u>20"</u>
		<u>575E</u>
		<u>294.66'</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Certificate - Dave Landecker - 1985
Doc. # 285168

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____