


Index No. N 15

CASS COUNTY LAND CORNER RECORD

T. 133 R. 31 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N 14 22 Corner common to sections 15 AND 22



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1863  
Original monument POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Species	Bearing	Trees
<u>ASPEN</u>	<u>ASPEN</u>	
Diameter <u>7"</u>	<u>8"</u>	
Bearing <u>S 77 E</u>	<u>S 30 W</u>	
Distance <u>16 LKS</u>	<u>32 LKS.</u>	

Species	Bearing	Trees	Found
_____	_____	_____	_____
Diameter _____	_____	_____	_____
Bearing _____	_____	_____	_____
Distance _____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration

Year of search 1985 By Dave Landecker  
Corner Certificate - Doc # 285671  
set cast iron monument

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Bearing Trees, Reference Objects

Br. oak	Br. oak	Br. oak	Br. oak
<u>20"</u>	<u>8"</u>	<u>4"</u>	<u>8"</u>
<u>S 40 E</u>	<u>S 13 W</u>	<u>S 70 W</u>	<u>N 73 W</u>
<u>60.46'</u>	<u>16.23'</u>	<u>45.31'</u>	<u>31.37'</u>

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Certificate - Dave Landecker - 1985  
Doc. # 285671

Remonumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_