



T. 133 R. 31 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_

NE 23 Corner common to sections 13, 14, 23, 24

EXISTING SURVEYS

Original Government Survey

Year surveyed 1863  
Original monument Post

Species	Bearing	Trees
<u>W. OAK</u>	<u>ASPEN</u>	<u>ASPEN</u>
Diameter <u>14"</u>	<u>12"</u>	<u>12"</u>
Bearing <u>S 74 1/2 W</u>	<u>N 81 1/4 W</u>	<u>S 50 E</u>
Distance <u>150 LKS</u>	<u>225 LKS</u>	<u>201 LKS</u>

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

O = Corner

Subsequent Corner Restoration

Year surveyed 1912 By JOHN CURA  
Location filed COUNTY SURVEY RECORD BOOK # P 496-498  
Monument FIND STUMP OF SW. OLD GAIT BIT AND ROOTS OF N.W. & SE. B.T.S. SET 2 1/2 X 36" GALV. IRON CONCRETE  
1917-E.B. HOEST-COUNTY BOOK "C" P. 83 FIND I.M.

Bearing Trees, Reference Objects

Species	Bearing	Distance
<u>ASPEN</u>	<u>ASPEN</u>	_____
Diameter <u>12"</u>	<u>6"</u>	_____
Bearing <u>S 11-55 E</u>	<u>N 69-33 E</u>	_____
Distance <u>85.64'</u>	<u>57.18'</u>	_____

Evidence of Subsequent Corner Restoration

Year of search 1985 By Dave Landecker  
Corner Certificate - Doc # 285676

End 2" 1/2 P. w/ base in concrete  
Set cast iron monument  
Survey marker sign N 25 E 65'

Bearing Trees, Reference Objects

Species	Bearing	Distance
<u>Ash</u>	<u>Br. oak</u>	<u>P. oak</u>
Diameter <u>4"</u>	<u>4"</u>	<u>18"</u>
Bearing <u>N 15 E</u>	<u>N 60 E</u>	<u>N 75 E</u>
Distance <u>75.04'</u>	<u>88.06'</u>	<u>172.21'</u>

N-21 Subsequent Corner Restoration N 21

Year surveyed 1915 By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument Co DITCH SURVEY BK 5 BOX 2 OF Co DITCH SURVEY BOOKS, PG 27

7/01 CCSSO found CIM, down 1.1', 1'E N. of 2 CR #101, on E 49th Ave. Also 1985 Svy Mkr sign and 18" R. Oak, added:

<u>5" Burr Oak</u>	<u>N 23° E</u>	<u>81.84' *</u>
<u>4" Burr Oak</u>	<u>N 58° E</u>	<u>87.27' *</u>
<u>Gate Post</u>	<u>N 40° W</u>	<u>53.95' *</u>

\*distance to double head nail

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Certificate - Dave Landecker - 1985  
Doc. # 285676.

- corner GPS 11/4/02 ccso  
CIM, down 1.0', 1' ± N of #101, on E 49th Ave.

June 1912, Twp rd order shows no survey