


Index No. R 25

CASS COUNTY LAND CORNER RECORD

T. 133 R. 31 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 25 Corner common to sections 24 125 AND 19 30-133-30



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1858  
Original monument POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

	Bearing Trees			
Species	<u>BIRCH</u>	<u>BIRCH</u>	<u>ASPEN</u>	<u>ASPEN</u>
Diameter	<u>8"</u>	<u>7"</u>	<u>8"</u>	<u>7"</u>
Bearing	<u>S 74 E</u>	<u>S 57 W</u>	<u>N 67 E</u>	<u>N 58 1/2 W</u>
Distance	<u>22 LKS</u>	<u>10 LKS</u>	<u>38 LKS</u>	<u>57 LKS</u>

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
PLAT - CASTLE ADDITION TO BIGWATER  
DEAN ANDERSON 1972  
8/1964 Dean Anderson  
Cert. of sur. shows mon. found

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_