


Index No. C 25

CASS COUNTY LAND CORNER RECORD

T. 133 R. 32 M. 5TH Coordinates: X _____ Y _____
E 1/4 Corner common to sections 1 AND 6-133-31



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1858
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species		Bearing		Trees	
	<u>PINE</u>		<u>PINE</u>		
Diameter	<u>7"</u>		<u>9"</u>		
Bearing	<u>N48 1/4 E</u>		<u>S60 W</u>		
Distance	<u>4 LKS.</u>		<u>16 LKS.</u>		

Original Bearing Trees Found			
Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 3/03 By B. Grivna
Location filed _____
Monument Found teispas stamped
County Surveyor, A Cert was
filed.

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species		Bearing		Reference Objects	
	<u>TWN OAK</u>		<u>BIRCH</u>		<u>OAK</u>
Diameter	<u>12"</u>		<u>10"</u>		<u>9"</u>
Bearing	<u>N56°W</u>		<u>S 24°E</u>		<u>S62°W</u>
Distance	<u>66.61'</u>		<u>14.35'</u>		<u>46.02'</u>

Bearing Trees, Reference Objects

_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

