


Index No. N 9

CASS COUNTY LAND CORNER RECORD

T. 134 R. 29 M. 5th Coordinates: X _____ Y _____
NE 20 Corner common to sections 16, 17, 20, 21



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1865
Original monument Post

Bearing Trees			
Species	<u>BL. PINE</u>	<u>BL. PINE</u>	<u>BL. PINE</u>
Diameter	<u>5"</u>	<u>5"</u>	<u>8"</u>
Bearing	<u>N41°4'E</u>	<u>N81°1/2W</u>	<u>S3°W</u>
Distance	<u>48 LKS.</u>	<u>34 LKS.</u>	<u>32 LKS.</u>

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1906 By JOHN CURO
Location filed COUNTY BOOK "B" P 361-363
Monument FIND OLD GOVT BT: 10" BL. PINE S3°W 32 LKS

Evidence of Subsequent Corner Restoration

Year of search 1977 By Co Hunt Dept
Co RD # 105
Brass cap monument

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

<u>N. Pine</u>	<u>Oak</u>	<u>Oak</u>
<u>4"</u>	<u>8"</u>	<u>12"</u>
<u>NW</u>	<u>SW</u>	<u>S</u>
<u>69.4'</u>	<u>112.0'</u>	<u>62.4'</u>

N-9

Subsequent Corner Restoration

Year surveyed 1994 By Grina 17253
Location filed CCSO
Monument Certificate of Survey indicates iron monument found.

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
PLAT - SQUAW POINT
FRANK GLASS 1915

Mar 2003 CCSO
Found 1/2" OD IR, 0.3' down, on E E
Co Rd #105 and Squaw Pt. rd.

* 12" N. Pine N48°W 69.50'
* 12" R. Oak S20°W 78.79'
P. Pole N16°E 110.88'
* Dist's meas. to dbl. hd nail.

PLAT - FIRST ADDITION TO THE VILLAGE OF EAST GULL LAKE
GUS HOLMSTROM 1947