Index No. A 25

# CASS COUNTY LAND CORNER RECORD

T. 134 R. 30 M. 5TH Coordinates: X _____ Y _____

NE 1 Corner common to sections 1 AND 36-135-30 AND 31-135-29 AND 6-134-29 W.C 264' SOUTH AND W.C 561' NORTH



O = Corner

## EXISTING SURVEYS

### Original Government Survey

Year surveyed 1858

Original monument W.C. POST SOUTH 4.CH. W.C. POST NORTH 8.50 CH.

Bearing Trees

| | South W.C. | | | North W.C. |
|---|---|---|---|---|
| Species | PINE | ASPEN | ASPEN | ASPEN |
| Diameter | 20" | 12" | 12" | 7" |
| Bearing | S 35 3/4 W | S 37 W | N 25 E | N 9 W |
| Distance | | 67 LKS. | 300 LKS | 400 LKS. |

### Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

| | | | |
|---|---|---|---|
| Species | | | |
| Diameter | | | |
| Bearing | | | |
| Distance | | | |

### Subsequent Corner Restoration

Year surveyed 1920 By _____

Location filed _____

Monument _____

Bearing Trees, Reference Objects

| | | | |
|---|---|---|---|
| Species | | | |
| Diameter | | | |
| Bearing | | | |
| Distance | | | |

### Evidence of Subsequent Corner Restoration

Year of search 1967 By D.M. Anderson

WC - 2 1/2" Iron Pipe with aluminum cap. 264' South of corner. See Misc. file.

Bearing Trees, Reference Objects

| | | | |
|---|---|---|---|
| R. Oak | Power Pole | Poplar | |
| 14" | | 14" | |
| SE | SSW | SW | |
| 42.45' | 36.85' | 51.65' | |

A-25

### Subsequent Corner Restoration

Year surveyed 1999 By DNR J. Walker

Location filed State of MN & CCSO

Monument Certificate of Survey indicates iron pipe found.

MAY 1999 CERT OF LOCATION DOC# 412430

Oct. 1903, W.H. Hallett Twp. rd. order shows survey

### Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____