

Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____


Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

T. 134 R. 30 M. 5TH Coordinates: X _____ Y _____
N 1/4 10 Corner common to sections 3, 10



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1868
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	<u>N. PINE</u>	<u>W. PINE</u>	_____
Diameter	<u>22"</u>	<u>6"</u>	_____
Bearing	<u>N43E</u>	<u>S43W</u>	_____
Distance	<u>44 LKS.</u>	<u>10 LKS.</u>	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1911 By A. W. MOULSTER
 Location filed COUNTY SURVEY RECORD BOOK "A" P 465-472
 Monument Find 1 1/4" I.D. Set From Bush old B.T.S.
1914 JOHN CURE BOOK "B" P 32-34 FIND SMALL IRON
SET 4x36" BL. IRON P. AG OLD GOVT B.T.S. (STUMPS) CHECK
1911- also on microfilm - Roll 105 BK 49 P. 59

Bearing Trees, Reference Objects

Species	<u>N. PINE</u>	_____	_____
Diameter	<u>11"</u>	_____	_____
Bearing	<u>N54-22E</u>	_____	_____
Distance	<u>35.60'</u>	_____	_____

1911 tie

Evidence of Subsequent Corner Restoration

Year of search 1990 By M. CURE
CO HWY CRW SET PIN TEMP B.T.S.

Bearing Trees, Reference Objects

_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search 1993 6-28 By Lowell Pommerening
 Found 1/2" iron rod, down 0.2' left as found
10-14-93 Cert. filed by Lowell
Pommerening, RLS # 17005, Doc. # 351912
Ties: Red Pine, 14", N06E; 6" Red Pine
S13W 83.19; 8" White Pine, S27E 69.78

Remonumentation certificate prepared _____
 Filed at _____

By _____
 Date _____