Index No. R 20-21

CASS COUNTY LAND CORNER RECORD

T. 134 R. 30 M. 5TH Coordinates: X _____ Y _____

M.C. #7 Corner common to sections 23, 26



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1868

Original monument Lost

Original Evidence Found

Year of search _____ By _____

Monument found _____

Bearing Trees

Species	ELM	ELM		
Diameter	6"	8"		
Bearing	N25W	S45W		
Distance	14 LKS.	33 LKS.		

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed 1967 By Co Hwy Dept

Location filed Co Rd # 77

Monument 2" Pip.

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species				
Diameter				
Bearing				
Distance				

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____