


Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:


Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

Index No. R 3

CASS COUNTY LAND CORNER RECORD

T. 134 R. 30 M. 5TH Coordinates: X _____ Y _____
N 1/4 30 Corner common to sections 19, 30



EXISTING SURVEYS

Original Government Survey

Year surveyed 1868
Original monument Post

Bearing Trees	
Species	<u>BL. PINE</u> <u>BL. PINE</u>
Diameter	<u>14"</u> <u>14"</u>
Bearing	<u>N5E</u> <u>S2W</u>
Distance	<u>42 LKS.</u> <u>64 LKS.</u>

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 2000 By CCSO
Location filed Cass Co. Hwy Dept. / Survey Dept.
Monument MAG NAIL set. Located 7' S & 68W
34 and 47' W of E ent. to the North.

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	<u>J. Pine</u>	<u>P. Oak</u>	<u>W. Oak</u>
Diameter	<u>8"</u>	<u>10"</u>	
Bearing	<u>N 38° W</u>	<u>N 8° E</u>	<u>S 53° E</u>
Distance	<u>112.38'</u>	<u>54.92'</u>	<u>97.05'</u>

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument 6/2002 B. Grivna
Cert. of SUR. Shows PK found

April 2004 B. Grivna # 17253
Cert. of SUR. Shows mon. found

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____