


Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____


Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

T. 134 R. 30 M. 5TH Coordinates: X _____ Y _____
NE 30 Corner common to sections 19, 20, 29, 30



EXISTING SURVEYS

Original Government Survey
 Year surveyed 1868
 Original monument Post

Species	Bearing Trees			
	<u>BL. PINE</u>	<u>BL. PINE</u>	<u>BL. PINE</u>	<u>BL. PINE</u>
Diameter	<u>14"</u>	<u>12"</u>	<u>7"</u>	<u>15"</u>
Bearing	<u>S44W</u>	<u>N87W</u>	<u>N78E</u>	<u>S77E</u>
Distance	<u>43 LKS.</u>	<u>29 LKS</u>	<u>56 LKS</u>	<u>54 LKS.</u>

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Evidence of Subsequent Corner Restoration
 Year of search 1994 4/4 By John D. Walker
 Found a Spike 0.6' N of center line of E-W C.S.A.H. 34 (Down 0.8'). Placed a 3/4" x 24" rebar w/ alum. cap stamped: "DNR Survey Marker" in place of spike. Mon. is 0.6' N of & CSAH 34; 12' E of & Driveway N 7-16' W of E.H. of & Driveway S in line w/ Old Fence S.

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>Power Pole</u>	<u>5"</u>	<u>N18E</u>	<u>51.32</u>
<u>Jack Pine</u>	<u>5"</u>	<u>S34W</u>	<u>70.23</u>
<u>Norway Pine</u>	<u>8"</u>	<u>S32E</u>	<u>86.74</u>

2-22-96 Cert. Filed by John Walker, RLS 16098
 Doc # 375017

R-5 Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found
 Year of search 1999 By CCSO
 Ind. incl. 3/4" w/ Alum. cap stamped: "DNR SURVEY MKR". Located 0.6' N of & Co RD 34, 12' E of & Driveway to the North and 16' W of & Driveway to the south. Cor. is in line w/ old fence line to the south.
 REF TIES: P. Pole N 72° W 181.35'
 P. Pole N 18° E 51.32'
 8" N. Pine S 22° E 86.74'
 5" J. Pine S 34° W 70.23'

Feb 2003 D. Lardner # 17009
 Cert. of Svy. shows Mon. Found

— Corner GPS 8/15/02 CCSO
 DNR Alum cap, 0.5' N. of #34

June 2003 P. Trottier # 41002
 Cert. of Svy. shows Mon. Found

Aug 2003 J. Kramer # 23668
 Cert. of Svy. shows Mon. Found

March 2004 J. Kramer # 23668
 Cert. of Svy. shows Mon. Found