


T. 134 R. 31 M. 5TH Coordinates: X _____ Y _____
N 1/4 Corner common to sections 1 AND 36-135-31



EXISTING SURVEYS

Original Government Survey

Year surveyed 1856
Original monument POST

Bearing Trees

Species	<u>W. BIRCH</u>	<u>W. BIRCH</u>	_____
Diameter	<u>9"</u>	<u>6"</u>	_____
Bearing	<u>S 46W</u>	<u>N 67W</u>	_____
Distance	<u>148KS</u>	<u>5"</u>	_____

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration

Year of search 1996 April By John D. Walker
Placed a 3/4" x 24" rebar w/ alum. cap
stamped: "DNR SURVEY MARKER" (up 0.2)
w/ steel fence post on south side
Cert. filed by John D. Walker, RLS 16098,
Doc. # 408851

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____