


Index No. A 5

CASS COUNTY LAND CORNER RECORD



T. 134 R. 31 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 6 Corner common to sections 5, 6 AND 31, 32-135-31

EXISTING SURVEYS

Original Government Survey  
 Year surveyed 1858  
 Original monument Post

Original Evidence Found  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Monument found \_\_\_\_\_

Species	Bearing	Trees	Distance
<u>PINE</u>	<u>PINE</u>	<u>PINE</u>	<u>ASPEN</u>
<u>10"</u>	<u>10"</u>	<u>9"</u>	<u>4"</u>
<u>S24W</u>	<u>S1E</u>	<u>N16E</u>	<u>N45W</u>
<u>43LKS</u>	<u>19LKS</u>	<u>45LKS</u>	<u>12LKS</u>

Original Bearing Trees Found  
 Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

Subsequent Corner Restoration  
 Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed \_\_\_\_\_  
 Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration  
 Year of search 1993 Oct. By Thomas Thiessen  
Placed a "12" iron pipe monument capped  
RLS # 16097  
4-26-94 Cert. Filed by Thomas Thiessen  
RLS 16097, Doc. # 357098

Bearing Trees, Reference Objects  
 Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

Bearing Trees, Reference Objects  
White Oak Red Oak Twin Red Oak  
14" 4" 14"  
44.15 28.25 37.37

A-5

Subsequent Corner Restoration  
 Year surveyed 5/2001 By CCSO  
 Location filed P.L.C. #2000.045  
 Monument Found 1993 capped 1P, 2'± N.  
and 33'± E. of fence lines. Also  
Witnesses NE & NW, add the following:  
12" Tw. R. Oak S32°E, 19.18'\*  
3" R. Oak S86°W, 26.38'\*  
July 1902; Typ rd order shows no survey

Evidence of Subsequent Corner Restoration Found  
 Year of search \_\_\_\_\_ By \_\_\_\_\_

Remuneration certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
 Filed at \_\_\_\_\_ Date \_\_\_\_\_